源摩哆廠 GUAN MOTOR WORKS

Not Notharks 11 Emp & ? Runny Afa Pain

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 Ft/P; 9742 6003

REPAIR ESTIMATE FOR GBF7797H

		HEI AIR COTTO			
No.	Qty				
		<u>List Items</u>	Bus	INU 517.20	
1	1	Rear bumper	Ś	517.20 Sn 60.00 Sn 154.00	X
2	2	Rear bumper side clips	Š	Pm 154.00	, χ
3	4	Rear bumper inner bracket	Š	Ma 30.00	1
4	1 se	t Rear bumper clips	\$	GT 577.20	· —
5	1	LH taillamp	č	£ 94.8€	
6	1	LH taillamp lower garnish	ç	By . 21:62	
7	1	Rear tailgate	\$ \$ \$	In 201.40	
8	1	Rear tailgate outer black handle	ç	Ma 66.20	
9	1	Rear tailgate centre "TOYOTA" logo	÷	14 28.00	
10	1	Rear tailgate LH "TOYOTA" emblem	ç	Ma 39.00	
11	1	Rear tailgate LH "HIACE" emblem	ب	M 289.70	
12	1	Rear tailgate top lock	\$	n 260.10	
13	1	Rear tailgate central lock	5	391.20	1 12
14	1	Rear tailgate weatherstrip	\$ \$ \$ \$ \$ \$ \$ \$	Su 186.70	
15	1	Rear tailgate iner trim hoard Consultants hence notify		7 Ma 50.00	
16	1 se	t Rear tailgate inner built Repuller of the following:		N 580.10	191
17	1	Rear end panel • To resurvey before/after spray painting	\$	5,380.90	
		To display damaged part(s) during resurvey Parts prices are subject to confirmations	, \$	1,345.23	
		Inite party survey is on a "Without Prejudic	5% \$		_
		No illegal modification(s) is allowed Total	7:503.3 \$	4,035.68	- 14
		Supplementary item(s) must be resurveyed is subject to final approval from Insurance C	and		
		Special Nett Items		SUR 250.00	2001A
18	1 set	Reverse sensors Acknowledged by Repairer Signature:	\$	550.00	
19	1 set	Reverse camera Date:	\$	0	
20	1	Rear number plate	\$	امر 50.00 مدر 60.00	•
21	1 set	Rear windscreen sealant	\$		
22	1 set	Rear end panel sealant	\$	80.00	100
23	1	Rear tailgate LH "70km/h" sticker	\$	Mc 15.00	_
		Total	1: \$	1,005.00	_
		Labour			£
1	Labo	ur Charges for remove/refit, cutting/welding and	\$	1,000.00	3001
	repla	cement of damages.			80
2	Тори	itty and spray Spray Paintings charges.	\$	1,000.00	
3	To re	move, refit rear windscreen glass.	\$	150.00	
4	To ch	eck wirings and lightings.	\$	40.00	The state of the s
5	To re	move, refit reverses sensors.	\$	60.00	
6	To re	move, refit reverse camera.	\$	80.00	The state of the s
7		move, refit rear tailgate fittings.	\$ \$ \$ \$	80.00	
8		move, refit rear upholstery and attachments.	\$	NA 120.00	X
9		pply and apply anti rust treatment	\$	90.00	301
177		Total	: \$	2,620.00	
					-0
		Total Parts and Labou	ır: \$	7,660.68	
			_		-