

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2020		27 Jul 2020 16:31 Edit Adj Rpt	S\$2,012.27 Edit Estimates	S\$2,012.27 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: 0 , Co. Reg. No.: 0									
Main Claimant: LEE WEN FEN									
Vehicle Reg. No.: SDM7600G		Date of Loss: 13/07/2020 12:00 - :59 [55 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D202452/C02/TANGHL2		Policy/Cover Note No.: DMPCSN30474219066							
Vehicle Reg. No. (Insured): SGJ8490E		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64563637									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 06/08/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDM7600G (SNM20D202452/C02/TANGHL2)
[SGJ8490E]
TP
LEE WEN FEN
Jul 13 2020 12:00PM
[0]
Ah Lim Motor Company

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/07/20 17:07	Adjuster Immediate Advice	 Load HTM	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/09/20 10:05	General View	 Load JPG	☒
2	10/09/20 10:05	General View	 Load JPG	☒
3	10/09/20 10:05	General View	 Load JPG	☒
4	10/09/20 10:05	General View	 Load JPG	☒
5	10/09/20 10:05	General View	 Load JPG	☒
6	10/09/20 10:05	General View	 Load JPG	☒
7	10/09/20 10:05	General View	 Load JPG	☒
8	10/09/20 10:05	General View	 Load JPG	☒
9	10/09/20 10:05	General View	 Load JPG	☒
10	10/09/20 10:05	General View	 Load JPG	☒
11	10/09/20 10:05	General View	 Load JPG	☒
12	10/09/20 10:05	General View	 Load JPG	☒
13	10/09/20 10:05	General View	 Load JPG	☒
14	10/09/20 10:05	General View	 Load JPG	☒
15	10/09/20 10:05	General View	 Load JPG	☒
16	10/09/20 10:05	General View	 Load JPG	☒
17	10/09/20 10:05	General View	 Load JPG	☒
18	10/09/20 10:05	General View	 Load JPG	☒
19	10/09/20 10:06	Odometer Reading	 Load JPG	☒
20	10/09/20 10:06	Reinspection Photo	 Load JPG	☒
21	10/09/20 10:06	Reinspection Photo	 Load JPG	☒
22	10/09/20 10:06	After Repair Photo	 Load JPG	☒
23	10/09/20 10:06	After Repair Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20007403/GTF3S2**Date:** 15/09/2020**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30474219066

Claimant Vehicle No : SDM7600G **Insured Vehicle No :** SGJ8490E

Date of Loss: 13/07/2020 Nature of Claim: TP Claim No: SNM20D202452/C02/TANGHL2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDM7600G**

Make & Model: TOYOTA HARRIER, 2.0 (A) Engine No: 3ZRB682780

Reg. Date: 16/11/2015 (Man. Year: 2015) Chassis No: ZSU600065315

Colour: Black Odometer: 72697 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R18 Rear Tyre Size: 235/55R18

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,911.23	1,402.27	508.96	26.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,090.00	610.00	480.00	44.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,001.23	2,012.27	988.96	32.95
+ GST 7.00/7.00% (S\$)	210.09	140.86	69.23	32.95
Nett Amount (S\$)	3,211.32	2,153.13	1,058.19	32.95

INSPECTION

Date of Assignment: 27/07/2020

Date Inspected: 17/07/2020 Inspected At: Ah Lim Motor Company (Sin Ming)
176 Sin Ming Drive #05-12, Sin Ming AutoCare
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Sep 2020)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDM7600G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,605.90 FL	*1,381.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Deformed	69.70 FL	*69.70 FL
3	1		*REAR BUMPER LOWER GARNISH	Deformed	411.67 FL	*389.00 FL
4	1		*REAR BUMPER SPONGE	Not Necessary	127.80 FL	*- FL
5	10		*REAR BUMPER CLIP	Necessary	39.90 FL	*30.00 FL
6	1		*SET REVERSE SENSOR	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,474.97	1,869.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	563.74	467.43
Total Parts (\$\$)	1,911.23	1,402.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND INSTALL REVERSE SENSOR	New	30.00	30.00
2	TO DISMANTLE AND INSTALL RR END PANEL INNER TRIM BOARD AND COVER	New	60.00	30.00
3	TO DISMANTLE AND INSTALL DAMAGE PARTS,TO KNOCK AND REPAIR TAIL END PANEL AND TO REFIT LISTED PARTS BACK SAME	New	500.00	250.00
4	TO SPRAY RR BUMPER,TAIL END PANEL	New	500.00	300.00
Gross Labour Cost (S\$)			1,090.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >