

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20007405/USF3E2

Date: 24/08/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant Vehicle No : SMH953D

Insured Vehicle No : SLP1417Z

Date of Loss: 16/07/2020

Nature of Claim: TP

Claim No: 626076

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH953D**

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B5559446

Reg. Date: 10/01/2019 (Man. Year: 2018)

Chassis No: RU11309435

Colour: Silver

Odometer: 15453 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side:

Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side:

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,398.24	5,577.60	5,820.64	51.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	2,590.00	1,160.00	30.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,148.24	8,167.60	6,980.64	46.08
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	15,148.24	6,500.00	8,648.24	57.09

INSPECTION

Date of Assignment: 17/07/2020

Date Inspected: 16/07/2020 Inspected At:

Zoom Autowerks Pte Ltd (HQ)

15 Kaki Bukit Road 4, #01-53

Singapore 417808

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH953D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	995.20 FL	*581.20 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	136.40 FL	*- FL
3	2		*REAR BUMPER BRACKET	Not Necessary	144.80 FL	*- FL
4	1		*REAR BUMPER LOWER DIFFUSER	Twisted	680.00 FL	*348.20 FL
5	1		*REAR BUMPER REFLECTORS	O/S Cracked	291.60 FL	*145.40 FL
6	1		*REAR BUMPER SIDES	Repair	391.60 FL	*- FL
7	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
8	1		*REAR TAILLAMPS	O/S Cracked	1,160.40 FL	*460.20 FL
9	1		*REAR TAILGATE	Badly Dented	1,128.90 FL	*953.00 FL
10	2		*REAR TAILGATE DAMPERS	Not Necessary	350.80 FL	*- FL
11	1		*REAR TAILGATE RUBBER	Twisted	215.30 FL	*135.70 FL
12	1		*REAR TAILGATE LOGO	Not Necessary	78.30 FL	*- FL
13	1		*REAR TAILGATE EMBLEM (VEZEL)	Necessary	101.20 FL	*56.20 FL
14	1		*REAR TAILGATE EMBLEM (HYBRID)	Not fitted	72.40 FL	*- FL
15	1		*REAR TAILGATE GLASS INNER SPONGE SEAL / RUBBER	Necessary	175.40 FL	*110.00 FL
16	1		*REAR TAILGATE INNER TRIMBOARD	Deformed / Torn	720.50 FL	*268.20 FL
17	1		*SET REAR TAILGATE INNER TRIMBOARD CLIPS	Not Necessary	60.00 FL	*- FL
18	1		*REAR TAILGATE INNER LOCK	Shorted / Twisted	332.10 FL	*198.50 FL
19	1		*REAR TAILGATE INNER LOCK COVER	No such part	92.40 FL	*- FL
20	1		*REAR TAILGATE CENTRE CHROME GARNISH	Not Necessary	387.30 FL	*- FL
21	2		*REAR TAILGATE NUMBER PLATE LAMP	Not Necessary	97.20 FL	*- FL
22	1		*REAR TAILGATE LOCK KEYLESS SENSOR	Not Necessary	189.80 FL	*- FL
23	2		*REAR TAILGATE REFLECTOR LAMP	Not Necessary	940.60 FL	*- FL
24	2		*REAR FENDER ARC-GARNISH	Torn	396.40 FL	*396.40 FL
25	1		*SET REAR LEFT FENDER INNER TRIM GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
26	2		*REAR FENDER INNER SHIELD	Not Necessary	490.60 FL	*- FL
27	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
28	1		*REAR END PANEL	Badly Dented	759.10 FL	*514.00 FL
29	1		*REAR END PANEL TOP GARNISH	Twisted	175.90 FL	*128.50 FL
30	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
31	1		*REAR SPARE TYRE PANEL TOOLS SPONGE	Torn	341.80 FL	*341.80 FL
32	1		*REAR SPARE TYRE PANEL CARDBOARD	Torn	489.60 FL	*341.10 FL
33	1		*REAR SPARE TYRE PANEL	Crumpled / Buckled	785.60 FL	*785.60 FL
34	1		*REAR EXHAUST END BOX	Bent / Twisted	745.60 FL	*699.50 FL
35	1		*REAR EXHAUST END BOX HEAT SHIELD	Bent	96.00 FL	*96.00 FL
36	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
38	1		*REAR EXHAUST CHROME MUFFLER	Not fitted	280.00 FS	*- FS
39	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	68.00 FS	*- FS
40	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,050.80	6,899.50
- List Item Discount on L Items 20.00/20.00% (S\$)	2,652.56	1,321.90
Total Parts (S\$)	11,398.24	5,577.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	1,280.00
2	TO PUTTY, SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	980.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH	New	200.00	60.00
5	TO REMOVE & INSTALL REAR TAILGATE GLASS	New	200.00	120.00
6	TO RE-POSITION, DRILL & INSTALL REVERSE SENSOR	New	150.00	50.00
7	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
8	TO RUST PROOF AFFECTED AREAS	New	200.00	80.00
Gross Labour Cost (S\$)			3,750.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >