

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007407/KGA3Q2
Date: 28/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900121850
Claimant Vehicle No :	SLP5429M	Insured Vehicle No :	SMM8953A
Date of Loss:	11/07/2020	Nature of Claim:	TP
		Claim No:	9599096482SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP5429M	Engine No:	R16B22000116
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650HT000094
Reg. Date:	08/06/2017 (Man. Year: 2017)	Odometer:	37916 km
Colour:	Metallic Blue		
Engine Capacity:	1397 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,056.24	567.20	1,489.04	72.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,110.00	450.00	28.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,616.24	1,677.20	1,939.04	53.62
Approved Total (Overridden) (S\$)		1,350.00		

(S\$)	3,616.24	1,350.00	2,266.24	62.67
+ GST 7.00/7.00% (S\$)	253.14	94.50	158.64	62.67
Nett Amount (S\$)	3,869.38	1,444.50	2,424.88	62.67
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
(S\$)		1,694.50		
Liable Amount (50.00%) (S\$)		847.25		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		849.25		

INSPECTION

Date of Assignment: 17/07/2020

Date Inspected: 22/07/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Bent	248.90 FL	*248.90 FL
2	1		*FRONT FENDER SIGNAL LAMP LH	Scratched	33.10 FL	*33.10 FL
3	1		*FRONT FENDER COWLING LH	Distorted	51.10 FL	*51.10 FL
4	8		*FRONT FENDER COWLING CLIPS	Necessary	28.00 FL	*28.00 FL
5	1		*SIDE SKIRT LH	Serviceable	117.80 FL	*- FL
6	1		*SIDE MIRROR ARM+SIGNAL LAMP +GLASS LH	Serviceable	254.30 FL	*- FL
7	1		*SIDE MIRROR COVER LH	Serviceable	59.90 FL	*- FL
8	1		*FRONT BUMPER	Repair	579.90 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	10.40 FL	*10.40 FL
10	12		*FRONT BUMPER CLIPS	Not Necessary	42.00 FL	*- FL
11	1		*HEADLAMP LH	Serviceable	585.70 FL	*- FL
12	1		*HEADLAMP LOWER BEAM LH	Repair	25.90 FL	*- FL
13	1		*FRONT WHEEL BEARING LH	Not Necessary	73.90 FL	*- FL
14	1		*FRONT WHEEL HUB LH	Serviceable	121.90 FL	*- FL
15	1		*FRONT BUMPER LOWER GARNISH (NPA)	Serviceable	0.00 FS	*- FS
16	1		*SPORT RIM LHF	Dented	180.00 FS	*180.00 FS
17	1		*TYRE LHF	Cut	90.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,502.80	641.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	446.56	74.30
Total Parts (\$\$)	2,056.24	567.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO CHECK AND READJUST WHEEL ALIGNMENT	New	80.00	60.00
3	TO DISMANTLE REPLACE AND REINSTALL UNDERCARRIAGE	New	80.00	0.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
5	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD TO KNOCK & REPAIR FRONT DOOR LH ROCKER PANEL LH INNER PANELS & AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	600.00	400.00
6	TO SPRAY FRONT BUMPER ,FRONT FENDER LH ,SIDE MIRROR COVER LH ,SIDE SKIRT LH ,FRONT DOOR LH ,ROCKER PANEL LH	New	700.00	600.00
Gross Labour Cost (\$\$)			1,560.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >