

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007409/KDA3Q2

Date: 15/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800095443

Claimant
Vehicle No : SKD1821P **Insured Vehicle No :** SMD2213P

Date of Loss: 16/07/2020 Nature of Claim: TP Claim No: 5436166623SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD1821P	Engine No:	1ZR131083
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104124087
Reg. Date:	02/11/2011 (Man. Year: 2011)	Odometer:	153835 km
Colour:	Metallic Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Davanti 3 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Davanti 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,459.96	3,713.62	746.34	16.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	2,080.00	1,480.00	41.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	8,019.96	5,793.62	2,226.34	27.76
Approved Total (Overridden) (\$)		4,600.00		
(S\$)	8,019.96	4,600.00	3,419.96	42.64
+ GST 7.00/7.00% (\$)	561.40	322.00	239.40	42.64
Nett Amount (\$)	8,581.36	4,922.00	3,659.36	42.64
+ Loss of Use (6.0 x S\$60.00/day) (\$)		360.00		
+ Doc/Search Fee (\$)		7.45		
Nett Liability (\$)		5,289.45		

INSPECTION

Date of Assignment: 17/07/2020

Date Inspected: 20/07/2020 Inspected At:

Wei Lee Motor Works (HQ)
BLOCK 9 SIN MING INDUSTRIAL
ESTATE #01-32
Singapore 575644

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent / Cracked	482.00 FL	*482.00 FL
2	2		*REAR BUMPER RETAINER	Distorted	145.40 FL	*145.40 FL
3	1		*REAR BUMPER SPONGE	Cracked	117.50 FL	*117.50 FL
4	1		*REAR BUMPER CLIP/SCREW	Necessary	38.00 FL	*38.00 FL
5	2		*REAR BUMPER REFLECTOR	Serviceable	74.40 FL	*- FL
6	1		*TAILGATE	Buckled	754.30 FL	*754.30 FL
7	1		*TAILGATE LOCK	Dented	96.50 FL	*96.50 FL
8	2		*TAILGATE REFLECTOR	Serviceable	233.20 FL	*- FL
9	1		*TAILGATE CHROME HANDLE	Cracked	332.98 FL	*332.98 FL
10	1		*TAILGATE 1.6 EMBLEM	Necessary	32.10 FL	*32.10 FL
11	1		*TAILGATE VVTI EMBLEM	Necessary	38.40 FL	*38.40 FL
12	1		*TAILGATE ALTIS EMBLEM	Necessary	42.35 FL	*42.35 FL
13	1		*TAILGATE -COROLLA EMBLEM	Necessary	45.00 FL	*45.00 FL
14	1		*BOOT WEATHERSTRIP (50%)	Dented / Cut	131.51 FS	*87.67 FS
15	2		*TAILLAMP	Mtg Cracked	563.80 FL	*563.80 FL
16	1		*END PANEL	Bent	581.20 FL	*581.20 FL
17	1		*SPARE TYRE PANEL	Bent / Buckled	702.90 FL	*702.90 FL
18	1		*SPARE TYRE BOARD	Cracked	227.20 FL	*227.20 FL
19	2		*REAR BUMPER BRACKET	Bent	165.60 FL	*165.60 FL
20	1		*END PANEL TOP GARNISH	Cracked	202.70 FL	*202.70 FL
21	1		*FENDER ,REAR LH	Repair	602.40 FL	*- FL
22	1		*REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,829.44	4,855.60
- List Item Discount on L Items 25.00/25.00% (S\$)	1,369.48	1,141.98
Total Parts (S\$)	4,459.96	3,713.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE /REINSTALL REAR WINDSCREEN GLASS	New	160.00	0.00
2	TO REMOVE INNER GARNISH ,REAR SEATER CUSHION ,REAR SPEAKER BOARD ENABLE REPAIR JOB CARRYPOUT ,REINSTALL JOB DONE	New	150.00	80.00
3	TO REMOVE DAMAGED PARTS N ATTACHMENTS CUT N WELD DAMAGED FENDER STRAIGHTEN REAR CHASSIS WHERE NECESSARY REPAIR /RESHAPE ALL DENTED /DAMAGED AREAS TO REPLACE /ALIGN ALL PARTS INTO POSITION	New	1,650.00	1,100.00
4	TO SPRAY PAINT	New	1,600.00	900.00
Gross Labour Cost (\$\$)			3,560.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >