

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20007410/R1SF3E2
Date: 22/07/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800067115
Claimant Vehicle No :	SJR6103J	Insured Vehicle No :	SDL9968M
Date of Loss:	16/07/2020	Nature of Claim:	TP
		Claim No:	7376178510SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR6103J	Engine No:	1NZD314005
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603039243
Reg. Date:	30/06/2009 (Man. Year: 2008)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/07/2020	
Date Inspected:	17/07/2020 Inspected At:	Eng Hup Seng Motor (HQ) Blk 1, No. 2 Pandan Loop, Pandan Light Industries Park Singapore 128219
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT LH DOOR	Repair	0.00 F	*- F	
2	1		*FRT LH DOOR WING MIRROR ASSY	Broken	0.00 F	*- F	
3	1		*FRT BUMPER	Torn	0.00 F	*- F	
4	1		*FRT BUMPER BRACKET LH	Necessary	0.00 F	*- F	
5	1		*FRT BUMPER SIDE RETAINER LH	Necessary	0.00 F	*- F	
6	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F	
7	1		*FRT LH FENDER	Buckled	0.00 F	*- F	
8	1		*FRT LH FENDER INNER PANEL	Repair	0.00 F	*- F	
9	1		*BONNET	Bent	0.00 F	*- F	
10	1		*LH HEADLAMP	Cracked	0.00 F	*- F	
11	1		*LH FRT RIM	Scratched	0.00 F	*- F	
12	1		*REAR LH DOOR	Repair	0.00 F	*- F	
13	1		*REAR LH DOOR OUTER HANDLE	Scratched	0.00 F	*- F	
14	1		*REAR BUMPER	Repair	0.00 F	*- F	
15	1		*REAR LH FENDER	Repair	0.00 F	*- F	
16	1		*FRT LH SHOCK ABSORBER	Bent	0.00 F	*- F	
17	1		*FRT LH DOOR OUTER HANDLE	Scratched	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >