

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD20007414/ASF3E2

Date: 03/08/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00015707

Claimant Vehicle No : SGN4155D **Insured Vehicle No :** SKQ1461B

Date of Loss: 16/07/2020 Nature of Claim: TP Claim No: 1202000019191

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGN4155D**

Make & Model: HYUNDAI AVANTE, 1.6 HD (A)

Engine No: G4FC6U058708

Reg. Date: 17/11/2006 (Man. Year: 2006)

Chassis No: KMHU41BR7U069672

Colour: Purple

Odometer: 247824 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R16

Rear Tyre Size: 205/45 R16

Front Left Side: Kumho 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,501.28	1,137.36	2,363.92	67.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	730.00	1,380.00	65.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,611.28	1,867.36	3,743.92	66.72
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	5,611.28	1,500.00	4,111.28	73.27

INSPECTION

Date of Assignment: 17/07/2020

Date Inspected: 20/07/2020 Inspected At:

Yi Heng Motor Workshop (HQ)

Blk 1 Kaki Bt Ave 6 #02-19

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2020)
Parts:	143	HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN4155D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP (RH)	Cracked	430.00 FL	*430.00 FL
2	1		*HEAD LAMP CLIP (RH)	Necessary	10.20 FL	*10.20 FL
3	1		*FRONT BUMPER	Deformed	873.00 FL	*470.90 FL
4	8		*FRONT BUMPER CLIP	Necessary	52.00 FL	*30.00 FL
5	1		*FRONT BUMPER REINTAINER	O/S Necessary	96.60 FL	*27.40 FL
6	1		*FRONT BUMPER SIDE REINTAINER RIVET (16PCS)	Necessary	52.80 FL	*10.00 FL
7	1		*FRONT BUMPER GARNISH (RH)	Cracked	78.00 FL	*47.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	184.00 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Cracked	238.00 FL	*113.40 FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	463.00 FL	*282.80 FL
11	1		*FRONT BUMPER REINFORCEMENT BRACKET (RH)	Not Necessary	231.00 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Not Necessary	783.00 FL	*- FL
13	1		*FRONT FENDER (RH)	Repair	437.00 FL	*- FL
14	10		*FRONT FENDER COWLING CLIP	Not Necessary	65.00 FL	*- FL
15	1		*FRONT GRILLE	Not Necessary	383.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,376.60	1,421.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	875.32	284.34
Total Parts (\$\$)	3,501.28	1,137.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	120.00	0.00
3	TO REMOVE AND REFIX HEAD LAMP ASSY AND REALIGNMENT LIGHTING SYSTEM	New	120.00	0.00
4	TO REMOVE AND REFIX AIR-CON CONDENSOR, PIPING SYSTEM AND TOP UP GAS	New	280.00	0.00
5	TO REMOVE AND REFIX RADIATOR ASSY AND CONDUCT PRESSOR TEST	New	180.00	0.00
6	TO REPLACE NEW PARTS, CUT, WELD, KNOCK AND ETC	New	880.00	300.00
7	TO RESPRAY ON AFFECTED AREAS	New	480.00	400.00
Gross Labour Cost (S\$)			2,110.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >