

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III20007418/QPA3Q2
Date: 11/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0000326
Claimant Vehicle No :	SMD7715A	Insured Vehicle No :	SMT2379K
Date of Loss:	04/07/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001261

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7715A		
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Engine No:	2AZF125761
Reg. Date:	26/09/2008 (Man. Year: 2008)	Chassis No:	ACR500062077
Colour:	Silver	Odometer:	159978 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,913.01	785.40	1,127.61	58.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	613.80	613.80	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,526.81	1,399.20	1,127.61	44.63
+ GST 7.00/7.00% (S\$)	176.88	97.94	78.94	44.63

Nett Amount (S\$)	2,703.69	1,497.14	1,206.55	44.63
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
Nett Liability (S\$)		1,697.14		

INSPECTION

Date of Assignment: 09/09/2020

Date Inspected: 09/09/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Hua Hong Pte Ltd (Sungei Kadut)
 25D Sungei Kadut Street 1
 Singapore 729332

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2021)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD7715A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cut	695.64 F	*695.64 F
2	1		*FRT BUMPER ABSORBER (WCP)	Serviceable	106.59 F	*- F
3	1		*FRT BUMPER CLAMP KIT (WCP)	Necessary	28.05 F	*28.05 F
4	1		*HEADLAMP HID BULB (WCP)	Serviceable	179.52 F	*- F
5	1		*R/F FOG LAMP (WCP)	Serviceable	112.20 F	*- F
6	1		*R/F OUT BUMPER BRKT (WCP)	Broken	61.71 F	*61.71 F
7	1		*RIGHT HEADLAMP ASSY (WCP)	Serviceable	729.30 F	*- F
					Total Parts (\$\$)	1,913.01
						785.40

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	22.0 WU X 50.00 SGD /H	New	200.00	200.00
2	LABOUR COST 54.0 WU X 50.00 SGD/H	New	270.00	270.00
3	MATERIAL COST	New	143.80	143.80
Gross Labour Cost (\$\$)			613.80	613.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >