

Your Ref: S0M02FOM

Date: 22<sup>nd</sup> July 2020

Our Ref: CS1/ASM20007422/Eqf3e2

**M/s Axa Insurance Pte Ltd**

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Liu Yi Wen

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SH 1296P  
INSURED VEHICLE: SDL 1381H  
ACCIDENT DATE: 06/02/2020**

We thank you for your instruction on 17/07/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SH 1296P from M/s KM Auto Assessors Pte Ltd.
- b) Survey report by LBS Automotive Appraisal Pte. Ltd. with colour photographs.
- c) Singapore Accident Statement of Vehicles SH 1296P and SDL 1381H.
- d) Final Repair Bill of SH 1296P from M/s Choon Hock Motor Trading Co.
- e) Colour damaged vehicle photographs of SH 1296P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SH 1296P
Make & Model	: Toyota Corolla Axio 1.5X CVT ABS D/Airbag 2WD
Chassis Number	: NRE1610005200
Year of Registration	: 2015
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.