

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20007425/QRA3Q2

**Date:** 28/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900082663

**Claimant**  
**Vehicle No :** SHB591E **Insured Vehicle No :** SMK1398J

Date of Loss: 08/07/2020 Nature of Claim: TP Claim No: 4202738299SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHB591E</b>                    |             |                   |
| Make & Model:               | TOYOTA PRIUS TAXI, 1.8 (A)        | Engine No:  | 2ZR6137981        |
| Reg. Date:                  | 12/09/2014 (Man. Year: 2014)      | Chassis No: | JTDKN36U505749160 |
| Colour:                     | Maroon                            | Odometer:   | 715615 km         |
| Engine Capacity:            | 1798 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                |                  |                |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size:  | 195/65 R15     | Rear Tyre Size:  | 195/65 R15     |
| Front Left Side:  | West Lake 6 mm | Rear Left Side:  | West Lake 6 mm |
| Front Right Side: | West Lake 6 mm | Rear Right Side: | West Lake 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts  | 5,081.20          | 2,053.96          | 3,027.24          | 59.58         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour   | 3,091.00          | 940.00            | 2,151.00          | 69.59         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>             | <b>8,172.20</b>   | <b>2,993.96</b>   | <b>5,178.24</b>   | <b>63.36</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>        |                   | <b>2,600.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                        | <b>8,172.20</b>   | <b>2,600.00</b>   | <b>5,572.20</b>   | <b>68.18</b>  |
| <b>+ Loss of Use (5.0 x S\$50.00/day) (\$\$)</b> |                   | 250.00            |                   |               |
| <b>+ Car Rental (5.0 x S\$89.14/day) (\$\$)</b>  |                   | 445.70            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                   |                   | 7.00              |                   |               |
| <b>Nett Liability (\$\$)</b>                     |                   | <b>3,302.70</b>   |                   |               |

### INSPECTION

Date of Assignment: 13/07/2020

Date Inspected: 13/07/2020 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 3.0 days

**Adjuster:** OI SUN PIN**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition   | Repairer's | Amount    |
|-----|-----|----------|------------------------------------|-------------|------------|-----------|
| 1   | 1   |          | *DOOR RR/RH (DISC 25%)             | Dented      | 954.50 F   | *715.88 F |
| 2   | 1   |          | *DOOR FRT/RH (DISC 25%)            | Dented      | 894.40 F   | *670.80 F |
| 3   | 1   |          | *DOOR HINGE UPPER RR/RH (DISC 25%) | Bent        | 81.70 F    | *61.28 F  |
| 4   | 1   |          | *DOOR HINGE LOWER RR/RH (DISC 25%) | Bent        | 72.20 F    | *54.15 F  |
| 5   | 1   |          | *DOOR LOCK FRT/RH (DISC 25%)       | Cracked     | 575.80 F   | *431.85 F |
| 6   | 1   |          | *PIXEL STICKER (SN)                | Necessary   | 60.00 F    | *60.00 F  |
| 7   | 1   |          | *STICKER DECAL SMRT (DOOR)<br>(SN) | Necessary   | 60.00 F    | *60.00 F  |
| 8   | 1   |          | *MOULDING BODY,RH                  | Serviceable | 673.60 F   | *- F      |
| 9   | 1   |          | *DOOR HINGE UPPER RR/RH            | Serviceable | 81.70 F    | *- F      |
| 10  | 1   |          | *DOOR HINGE LOWER RR/RH            | Serviceable | 72.20 F    | *- F      |
| 11  | 1   |          | *DOOR BELT RR/RH                   | Serviceable | 69.20 F    | *- F      |
| 12  | 1   |          | *CHECK ASSY ,RR DOOR               | Serviceable | 150.30 F   | *- F      |
| 13  | 1   |          | *DOOR WEATHERSTRIP RR/RH           | Serviceable | 171.20 F   | *- F      |
| 14  | 1   |          | *DOOR BELT FRT/RH                  | Serviceable | 69.20 F    | *- F      |
| 15  | 1   |          | *DOOR LOCK FRT/RH                  | Serviceable | 575.80 F   | *- F      |
| 16  | 1   |          | *DOOR LOCK STRIKER                 | Serviceable | 40.50 F    | *- F      |
| 17  | 1   |          | *DOOR WEATHER STRIP FRT/RH         | Serviceable | 171.20 F   | *- F      |
| 18  | 1   |          | *PILLAR ,CTR BODY                  | Serviceable | 307.70 F   | *- F      |

F=Franchise part.

|                           |                 |                 |
|---------------------------|-----------------|-----------------|
| <b>Total Parts (\$\$)</b> | <b>5,081.20</b> | <b>2,053.96</b> |
|---------------------------|-----------------|-----------------|

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars                             | Lab.Type | Repairer's      | Amount        |
|-------------------------------|---|----------|-----------------|---------------|
| <b><u>Labour Items</u></b>    |   |          |                 |               |
| 1                             | PANEL BEATING & BODY WORK               | New      | 845.00          | 400.00        |
| 2                             | SPRAY PAINT                             | New      | 1,116.00        | 400.00        |
| 3                             | TO CHECK WIRING AND SYSTEM FUNCTION     | New      | 80.00           | 20.00         |
| 4                             | TO APPLY RUST-PROOFING ON AFFECTED AREA | New      | 100.00          | 0.00          |
| 5                             | TO TRANSFER DOOR MECHANISM              | New      | 240.00          | 100.00        |
| 6                             | TO REMOVE AND REFIT WIRE HARDESS        | New      | 200.00          | 20.00         |
| 7                             | TO REPLACE SUNDRY PARTS                 | New      | 100.00          | 0.00          |
| 8                             | TO WASH AND VACUUM                      | New      | 60.00           | 0.00          |
| 9                             | TO CHECK & RESET SYSTEM FUNCTION        | New      | 350.00          | 0.00          |
| <b>Gross Labour Cost (\$)</b> |   |          | <b>3,091.00</b> | <b>940.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >