

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20007437/ASF3E2

Date: 15/12/2020

REFERENCE

Insured/Claimant:	LIM CHIA NIE	Policy No:	1800109579		
Date of Loss:	17/07/2020	Nature of Claim:	OD	Claim No:	3647722501SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF103B		
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Engine No:	CYR069824
Reg. Date:	13/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ4M3JD060912
Colour:	Black	Odometer:	13864 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$192,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55R19	Rear Tyre Size:	255/55R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,700.00	11,009.84	11,690.16	51.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,672.00	4,172.00	3,500.00	45.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,372.00	15,181.84	15,190.16	50.01
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	29,872.00	14,681.84	15,190.16	50.85
+ GST 7.00/7.00% (S\$)	2,091.04	1,027.73	1,063.31	50.85
Nett Amount (S\$)	31,963.04	15,709.57	16,253.47	50.85

INSPECTION

Date of Assignment:	20/07/2020		
Date Inspected:	21/07/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,434.00 FS	*1,947.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	442.00 FS	*- FS
3	1		*FRONT BUMPER TOWING EYE COVER	Cut	39.00 FS	*30.88 FS
4	1		*FRONT BUMPER AIR GUIDE-RH	Cracked	66.00 FS	*52.40 FS
5	1		*FRONT BUMPER END CAP-RH	Cracked	35.00 FS	*27.84 FS
6	1		*FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE	Not Necessary	273.00 FS	*- FS
7	1		*FRONT BUMPER GRILLE-LOWER CENTRE	Not Necessary	203.00 FS	*- FS
8	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	798.00 FS	*- FS
9	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	208.00 FS	*- FS
10	1		*FRONT BUMPER FRONT SPOILER-RH	Deformed	137.00 FS	*109.60 FS
11	1		*FRONT SPOILER TRIM-RH OUTER	Not Necessary	43.00 FS	*- FS
12	1		*RADIATOR GRILLE	Not Necessary	2,445.00 FS	*- FS
13	1		*RADIATOR GRILLE COVER	Not Necessary	72.00 FS	*- FS
14	1		*RADIATOR GRILLE INNER COVER	Not Necessary	61.00 FS	*- FS
15	1		*FRONT BUMPER AIR GUIDE GRILLE	Cut	294.00 FS	*234.80 FS
16	1		*FRONT BUMPER END CAP-RH	Damaged	33.00 FS	*26.32 FS
17	1		*SPOILER DEFLECTOR-RH INNER	Not Necessary	57.00 FS	*- FS
18	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	170.00 FS	*- FS
19	1		*FRONT BUMPER CARRIER	Not Necessary	858.00 FS	*- FS
20	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	72.00 FS	*- FS
21	1		*FRONT BUMPER GUIDE SECTION-RH	Damaged	44.00 FS	*34.48 FS
22	2		*FRONT PARKING AID SENSOR-INNER/OUTER (NPA)	Not Necessary	0.00 FS	*- FS
23	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
24	1		*FRONT FENDER-RH	Repair	1,602.00 FS	*- FS
25	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
26	1		*FRONT FENDER BRACE	Bent	100.00 FS	*79.92 FS
27	1		*FRONT FENDER BRACKET-RH	Not Necessary	64.00 FS	*- FS
28	1		*LED HEADLIGHT	Cracked	9,813.00 FS	*7,850.40 FS
29	1		*LIFT CYLINDER-RH	Not Necessary	196.00 FS	*- FS
30	1		*FRONT DOOR COVER-RH	Not Necessary	447.00 FS	*- FS
31	2		*FRONT WHEEL COVER-LH/RH	Necessary	654.00 FS	*522.40 FS
32	1		*WHEEL HOUSING LINER-RH	Not Necessary	237.00 FS	*- FS
33	1		*WHEEL HOUSING LINER-RH REAR	Not Necessary	237.00 FS	*- FS
34	1		*HEADLIGHT MOUNTING-RH	Cracked	117.00 FS	*93.60 FS
35	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
36	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 22,700.00 11,009.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER/REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT,POWER MODULE AND ELECTRICAL FANS FOR LED AND CONNECTORS	New	550.00	250.00
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	450.00	450.00
4	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS FRONT FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,700.00	1,200.00
5	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER AND RHS FRONT DOOR	New	3,500.00	1,800.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,672.00	4,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >