

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Dec 2019		06 Dec 2019 10:34 Edit Adj Rpt	S\$2,750.00 Edit Estimates	S\$2,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: JONG FRESH SUPPLIES PTE LTD , Co. Reg. No.: 200107204H									
Main Claimant: ONG LAY TIN , ID: S6802144H									
Vehicle Reg. No.:	SMK3416C	Date of Loss:	04/12/2019 11:00 - :59 [38 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 613559	Policy/Cover Note No.:	29075429MKC (Comprehensive) Coverage: 10/04/2019 - 09/04/2020						
Vehicle Reg. No. (Insured):	GBF9425T	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer: Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339, 470130 Eunos - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 21/07/2020]									
Adj Asg. Remarks: on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Elin Cai @ 9450 7920.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (18/07/2020): Report Send Back Alerts - SMK3416C (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMK3416C (613559)**
[GBF9425T]
TP
ONG LAY TIN
Dec 4 2019 11:00AM
[JONG FRESH SUPPLIES PTE LTD]
Zoom Autowerks Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images					
			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/12/19 12:11	Chassis Number		Load JPG	
2	09/12/19 12:12	Odometer Reading		Load JPG	
3	09/12/19 12:12	General View		Load JPG	
4	09/12/19 12:12	General View		Load JPG	
5	09/12/19 12:12	General View		Load JPG	
6	09/12/19 12:12	General View		Load JPG	
7	09/12/19 12:12	General View		Load JPG	
8	09/12/19 12:12	General View		Load JPG	
9	09/12/19 12:12	General View		Load JPG	
10	09/12/19 12:12	General View		Load JPG	
11	09/12/19 12:12	General View		Load JPG	
12	09/12/19 12:12	General View		Load JPG	
13	09/12/19 12:12	General View		Load JPG	
14	09/12/19 12:12	General View		Load JPG	
15	09/12/19 12:12	General View		Load JPG	
16	09/12/19 12:12	General View		Load JPG	
17	09/12/19 12:12	General View		Load JPG	
18	09/12/19 12:12	General View		Load JPG	
19	09/12/19 12:12	General View		Load JPG	
20	09/12/19 12:12	General View		Load JPG	
21	09/12/19 12:12	General View		Load JPG	
22	09/12/19 12:12	General View		Load JPG	
23	09/12/19 12:13	General View		Load JPG	
24	09/12/19 12:13	General View		Load JPG	
25	09/12/19 12:13	General View		Load JPG	
26	09/12/19 12:13	General View		Load JPG	
27	09/12/19 12:13	General View		Load JPG	
28	09/12/19 12:13	General View		Load JPG	
29	09/12/19 12:13	General View		Load JPG	
30	09/12/19 12:13	General View		Load JPG	
31	09/12/19 12:13	General View		Load JPG	
32	09/12/19 12:13	General View		Load JPG	
33	09/12/19 12:13	General View		Load JPG	
34	09/12/19 12:13	General View		Load JPG	
35	09/12/19 12:13	General View		Load JPG	
36	09/12/19 12:13	General View		Load JPG	
37	09/12/19 12:13	General View		Load JPG	
38	09/12/19 12:13	General View		Load JPG	
39	09/12/19 12:13	General View		Load JPG	
40	09/12/19 12:13	General View		Load JPG	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	09/12/19 12:13	General View		Load JPG	☒
42	09/12/19 12:13	General View		Load JPG	☒
43	09/12/19 12:13	General View		Load JPG	☒
44	21/01/20 10:28	After Repair Photo		Load JPG	☒
45	21/01/20 10:28	After Repair Photo		Load JPG	☒
46	21/01/20 10:28	After Repair Photo		Load JPG	☒
47	21/01/20 10:28	After Repair Photo		Load JPG	☒
48	21/01/20 10:28	After Repair Photo		Load JPG	☒
49	21/01/20 10:28	After Repair Photo		Load JPG	☒
50	21/01/20 10:28	After Repair Photo		Load JPG	☒
51	21/01/20 10:28	After Repair Photo		Load JPG	☒
52	21/01/20 10:28	After Repair Photo		Load JPG	☒
53	21/01/20 10:28	After Repair Photo		Load JPG	☒
54	21/01/20 10:28	After Repair Photo		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	05/12/19 15:20	TPD SMK3416C - ACCIDENT REPORT		Load PDF	
2	05/12/19 15:20	TPD SMK3416C - PRI		Load PDF	
3	06/12/19 09:31	Agree on SJE		Load PDF	
4	06/02/20 19:22	OI GIA		Load PDF	
5	18/07/20 21:02	LOD		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/07/20 08:34	PRS INVOICE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	--------------------------------------	-------------------------------------	--------------------------------------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG19021551/EQF3S2-1**Date:** 22/07/2020REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29075429MKG

Claimant Vehicle No : SMK3416C**Insured Vehicle No :** GBF9425T

Date of Loss: 04/12/2019

Nature of Claim: TP

Claim No: 613559

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMK3416C**

Make & Model: FORD MUSTANG, 2.3 (A)

Engine No: G5300984

Reg. Date: 22/09/2016 (Man. Year: 2016)

Chassis No: 1FA6P8TH9G5300984

Colour: Grey

Odometer: 28097 km

Engine Capacity: 2261 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 255/40ZR19

Rear Tyre Size: 255/40 R19

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,700.00	2,200.00	2,500.00	53.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,225.00	1,555.00	55.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,480.00	3,425.00	4,055.00	54.21
Approved Total (Overridden) (S\$)		2,750.00		
Nett Amount (S\$)	7,480.00	2,750.00	4,730.00	63.24

INSPECTION

Date of Assignment: 06/12/2019

Date Inspected: 06/12/2019 Inspected At:

Blk 15 Kaki Bukit Road 4 #01-53

Repairer: Zoom Autowerks Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2020)
Parts:	M1-COUPE	FORD MUSTANG 2.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK3416C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE MIRROR ASSY	Broken / Cracked	1,250.00 FS	*1,250.00 FS
2	1		*LH SIDE DOOR GLASS	Scratched / Cut	950.00 FS	*950.00 FS
3	1		*CARBON FIBRE SIDE SKIRT - LHS	Serviceable	2,500.00 FS	*- FS
Total Parts (S\$)						4,700.00
						2,200.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	60.00	45.00
2	TO APPLY ANTI-RUST UNDERCOAT.	New	120.00	30.00
3	TO SUPPLY LABOUR TO INSTALL RHS FIBRE CARBON SIDE SKIRT.	New	500.00	0.00
4	LABOUR CHARGES TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEAT THE FRONT DOOR, REAR FENDER BACK TO SHAPE.	New	900.00	400.00
5	SPRAY PAINTING CHARGES TO PAINT THE FRONT LH DOOR, LH SIDE MIRROR, LH REAR FENDER AND NECESSARY AREAS.	New	1,200.00	750.00
Gross Labour Cost (\$)			2,780.00	1,225.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >