

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007447/T1ES3Q2
Date: 09/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900097581
Claimant Vehicle No :	SH7720S	Insured Vehicle No :	SML3230R
Date of Loss:	17/07/2020	Nature of Claim:	TP
		Claim No:	9414356727SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7720S		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU110363
Reg. Date:	18/10/2018 (Man. Year: 2018)	Chassis No:	KMHC851CVKU114775
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,423.80	1,206.76	217.04	15.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,220.00	310.00	20.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,953.80	2,426.76	527.04	17.84
+ GST 7.00/7.00% (S\$)	206.77	169.87	36.90	17.85

Nett Amount (S\$)	3,160.57	2,596.63	563.94	17.84
		<hr/>		
+ Loss of Use (1.5 x S\$50.00/day) (S\$)		75.00		
+ Car Rental (S\$)		288.90		
+ Doc/Search Fee (S\$)		7.49		
		<hr/>		
Nett Liability (S\$)		2,968.02		
		<hr/>		

INSPECTION

Date of Assignment: 20/07/2020

Date Inspected: 20/07/2020

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -FR BUMPER	Deformed	430.90 FL	*430.90 FL
2	1		*MOULDING -FRONT	Not Necessary	93.60 FL	*- FL
3	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
4	1		*BRACKET -FR BUMPER	Not Necessary	35.00 FL	*- FL
5	1		*BRACKET -FR BUMPER	Not Necessary	28.00 FL	*- FL
6	1		*PANEL -FENDER RH	Bent	588.80 FL	*588.80 FL
7	1		*GUARD ASSY-FRONT	Not Necessary	114.70 FL	*- FL
8	1		*EMBLEM -BLUE DRIVE	Necessary	26.60 FL	*26.60 FL
9	1		*CAP ASSY -WHEEL	Cut	346.40 FL	*346.40 FL
10	1		*FRT DOOR LOGO CTPL	Necessary	75.00 FS	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,761.00	1,489.70
- List Item Discount on L Items 20.00/20.00% (\$)	337.20	282.94
Total Parts (\$)	1,423.80	1,206.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING (REPAIR FRT DOOR RH)	New	700.00	480.00
2	SPRAYPAINT ON AFFECTED AREA	New	650.00	600.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
5	ADJUST FRONT WHEEL ALIGNMENT	New	80.00	80.00
Gross Labour Cost (S\$)			1,530.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >