

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007448/KVF3E2

Date: 06/08/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30705619000	
Claimant Vehicle No : YP5229U	Insured Vehicle No : SMJ7854A	
Date of Loss: 22/06/2020	Nature of Claim: TP	Claim No: SNM20D202207/C02/TANGHL2

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP5229U		
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)	Engine No: 4P10C24824	
Reg. Date: 29/11/2016 (Man. Year: 2016)	Chassis No: FEB21EA20786	
Colour: Grey	Odometer: 34788 km	
Engine Capacity: 2998 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): <b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/85 R15	Rear Tyre Size: 195/85 R15 (D)
Front Left Side: Yokohama 9 mm	Rear Left Side: Bridgestone 8/8 mm
Front Right Side: Yokohama 9 mm	Rear Right Side: Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	985.59	821.32	164.27	16.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	140.00	460.00	76.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,585.59</b>	<b>961.32</b>	<b>624.27</b>	<b>39.37</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>110.99</b>	<b>67.29</b>	<b>43.70</b>	<b>39.37</b>
<b>Nett Amount (S\$)</b>	<b>1,696.58</b>	<b>1,028.61</b>	<b>667.97</b>	<b>39.37</b>

### INSPECTION

Date of Assignment: 05/08/2020		
Date Inspected: 29/07/2020	Inspected At:	385 Sin Ming Drive
		Repairer : Esteem Performance Pte Ltd (HQ)
Estimated Period of Repair: 1.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$961.33

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Aug 2020)	
<b>Parts:</b>	N/A	MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP5229U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR CLEANER BOX	Cracked	1,095.10 FL	*1,095.10 FL
					<b>Sub Total (\$\$)</b>	<b>1,095.10</b>
					<b>- List Item Discount on L Items 10.00/25.00% (\$\$)</b>	<b>273.78</b>
					<b>Total Parts (\$\$)</b>	<b>821.32</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(RH SUPPORT BAR)	New	300.00	60.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(RH SUPPORT BAR)	New	300.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>600.00</b>	<b>140.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**