

(33/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT120007449/Uqf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBJ 2534C

at Workshop m/s mahlian road

of _____

Insured: SMD 637

Policy No. DMPCSA00002781900

Claims No. SNM20D202459C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 45K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 27A22537

Veh No: GBJ 2534C Yr Regn: 2/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan NV200 c.c. 1461

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 16263 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM 2020174205

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14

R: _____

BS / DUN / EXNOVA / GYFS / EIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: 6 mm Rear: 6 mm

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/7/20 D.O.I. 24/7/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt, N/S Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

21/8/20 4/5 @ 7200 confirmed with Schui. (Red \$13319.85, 65%)

21/08/20@11.44am revised to Irene Tay via Merimen.

Date/Time, File Pass to?

☐

: Preli. Report

1) 21/08 Typist

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format: MER-TP

Lump Sum: 7200 (\$)

TOTAL

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO.201327339E

not Authorized
 22/7/20
 1/5 \$7200
 5 days

M/S : China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

TEL: - FAX: -
 ATTN: Motor Claim Department
 Your Ref No: VICTOR ENTERPRISE PL
 Claim Type: Third Party
 Accident Date: 14/07/2020
 TP Veh Reg No: SMD63T

Estimate No: ES1700687
 Date: 14 Jul 2020
 Policy No: 8-V0021449-MVA-R001
 Veh Reg No: GBJ2534L
 Make/Model: NISSAN NV200 1.5 MT
 Chassis No: VSKYBAM20Z0174205
 Engine No: K9KE628D631856
 Reg. Date: 26/02/2019

Estimate Repair Cost to Vehicle No :GBJ2534L

Description	U/Price	Quantity	List Price	Amount
			\$S	\$S
Net Item Net Price				
1 Front Bumper	563.50	851.76	1 PC 0.5 851.76	✓
2 Front Bumper Retainer - LH		30.42	1 PC 1.1 30.42	X
3 Front Bonnet		1,123.46	1 PC 1.1 1,123.46	X
4 Front Fender - LH	548.20	721.76	1 PC 0.5 721.76	✓
5 Front Wheel Inner Fender - LH		567.84	1 PC 1.1 567.84	X
6 Front Door Assy - LH	1219.70	1,673.75	1 PC 0.5 1,673.75	✓
7 Front Door Pillar - LH	1665.00	2,156.83	1 PC 0.5 2,156.83	✓
8 Front Door Window Glass - LH	680.00	1,040.00	1 PC 0.5 1,040.00	✓
9 Front Door Window Seal - LH	161.50	179.01	1 PC 0.5 179.01	✓
10 Fog Lamp - LH		335.40	1 PC 1.1 335.40	X
11 Fog Lamp Rim - LH		125.84	1 PC 1.1 125.84	X
12 Side Mirror Assy - LH		487.89	1 PC 0.5 487.89	✓
13 Headlamp Garnish - LH	348.60	479.05	1 PC 0.5 479.05	✓
14 Headlamp - LH		579.15	1 PC 0.5 579.15	✓
15 Sliding Door - LH	1281.70	1,934.66	1 PC 0.5 1,934.66	✓
16 Rear Fender - LH		2,123.03	1 PC 1.1 2,123.03	X
			14,409.85	14,409.85
Net Price				
17 Logo Advertisement	950.00	1 SET	950.00	300
18 ROC Sticker	50.00	1 SET	50.00	30
			1,000.00	1,000.00
Labour				
19 Labour to dismantle & weld & knock & renew all above parts .	2,300.00	1 JOB	2,300.00	880
20 Labour to refocus & connect wiring , headlamp .	120.00	1 JOB	120.00	20
21 To spray & painting on affected area .	1,800.00	1 JOB	1,800.00	980
22 To rust proofing on affected area .	890.00	1 JOB	890.00	90
			5,110.00	5,110.00

P-7535.24
 10%
 P-6781.71
 S.NK- 330.00
 L- 1970.00
 9081.71

MAH LIAN MOTOR VEHICLE REPAIRER

No 38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO 201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

TEL: - FAX: -

ATTN: Motor Claim Department

Your Ref No: VICTOR ENTERPRISE PL

Claim Type: Third Party

Accident Date: 14/07/2020

TP Veh Reg No: SMD63T

Estimate No: ES1700687

Date: 14 Jul 2020

Policy No: 8-V0021449-MVA-R001

Veh Reg No: GBJ2534L

Make/Model: NISSAN NV200 1.5 MT

Chassis No: VSKYBAM20Z0174205

Engine No: K9KE628D631856

Reg. Date: 26/02/2019

Estimate Repair Cost to Vehicle No :GBJ2534L

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			Total	S\$ 20,519.85
			Add GST @ 7%	1,436.39
			Total Amount Payable	S\$ 21,956.24

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND NINE HUNDRED FIFTY SIX AND CENTS TWENTY FOUR ONLY

For MAH LIAN MOTOR VEHICLE
REPAIRER

AUTHORISED SIGNATURE

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: