

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20007456/UBS3Q2

Date: 08/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMQ4210R	Insured Vehicle No :	SH6033Z
Date of Loss: 18/07/2020	Nature of Claim: TP	Claim No: MCT20070232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ4210R		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 COUPE AMG (A)	Engine No:	27492031370885
Reg. Date:	15/11/2019 (Man. Year: 2018)	Chassis No:	WDC2533462F402062
Colour:	Grey	Odometer:	14102 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,428.42	9,026.44	12,401.98	57.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	2,020.00	2,280.00	53.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,728.42	11,046.44	14,681.98	57.07
Approved Total (Overridden) (S\$)		8,800.00		
Nett Amount (S\$)	25,728.42	8,800.00	16,928.42	65.80
+ Car Rental (5.0 x S\$150.00/day) (S\$)		750.00		
Nett Liability (S\$)		9,550.00		

INSPECTION

Date of Assignment:	20/07/2020	
Date Inspected:	20/07/2020 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Aug 2020)	
Parts:	N/A	MERCEDES-BENZ GLC 250 2.0 COUPE AMG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ4210R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,510.00 F	*- FL
2	1		*TAILGATE REAR LOGO	Necessary	68.00 F	*68.00 FL
3	1		*TAILGATE GLC 250 EMBLEM	Necessary	92.00 F	*92.00 FL
4	1		*TAILGATE 4 MATIC EMBLEM	Necessary	95.00 F	*95.00 FL
5	2		*TAILGATE REFLECTORS	Not Necessary	1,010.00 F	*- FL
6	1		*TAILGATE INNER LOCK	Not Necessary	385.00 F	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	399.00 F	*- FL
8	1		*TAILGATE WEATHERSTRIP	Not Necessary	392.00 F	*- FL
9	1		*REAR BUMPER TOP	Distorted	1,565.00 F	*1,236.60 FL
10	1		*REAR BUMPER CENTRE PAD	Distorted	825.00 F	*592.11 FL
11	1		*REAR BUMPER LOWER	Distorted	655.00 F	*622.35 FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	170.00 F	*- FL
13	1		*SET REAR BUMPER RIVET	Necessary	60.00 F	*60.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	715.00 F	*715.00 FL
15	2		*REAR BUMPER REFLECTORS	Cracked	164.00 F	*164.00 FL
16	4		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	752.00 F	*376.00 FL
17	1		*REAR BUMPER PDC WIRE	Serviceable	315.32 F	*- FL
18	2		*REAR BUMPER INNER SIDE BRACKETS	Cracked	190.00 F	*190.00 FL
19	1		*REAR BUMPER SPONGE	Torn	288.35 F	*288.35 FL
20	1		*REAR BUMPER INNER KICKING SENSOR	Shorted	382.50 F	*382.50 FL
21	1		*REAR WINDSCREEN W/MOULDING	Not Necessary	855.00 F	*- FL
22	1		*REAR END PANEL	Dented / Bent	1,405.00 F	*1,399.22 FL
23	1		*REAR END PANEL TOP GARNISH	Not Necessary	306.00 F	*- FL
24	1		*REAR FLOOR PANEL	Not Necessary	1,485.00 F	*- FL
25	2		*REAR FENDER OUTER PROTECTORS	Torn / Necessary	798.00 F	*798.00 FL
26	2		*REAR FENDER INNER TRIM BOARDS	Not Necessary	1,920.00 F	*- FL
27	2		*REAR EXHAUST CHROMES	Bent	960.00 F	*900.00 FL
28	1		*REAR EXHAUST HEAT SHIELD	Bent	466.25 F	*335.25 FL
29	1		*REAR EXHAUST ASSY	Dented / Bent	1,850.00 F	*1,615.00 FL
30	1		*REAR LICENCE PLATE W/HOLDER	Broken	50.00 FS	*40.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
32	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
33	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,428.42	10,019.38
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	992.94
Total Parts (\$\$)	21,428.42	9,026.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	150.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REPLACED REAR EXHAUST	New	120.00	80.00
7	TO SPRAY RUST PROOFING	New	100.00	30.00
8	TO RESET & REPROGRAMME SYSTEM	New	200.00	50.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (\$\$)			4,300.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >