

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20007461/UQF3E2

**Date:** 25/08/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00005432000	
Claimant Vehicle No :	SLT5466J	Insured Vehicle No :	SJV663C	
Date of Loss:	17/07/2020	Nature of Claim:	TP	Claim No: SNM20D202504/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT5466J		
Make & Model:	MAZDA 6, 2.0 SEDAN EXECUTIVE EU6 (A)	Engine No:	PE20970408
Reg. Date:	31/10/2017 (Man. Year: 2017)	Chassis No:	JM6GL1071J0127802
Colour:	Red	Odometer:	50189 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40Z R19	Rear Tyre Size:	245/40Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,506.30	4,315.40	15,190.90	77.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,590.00	1,480.00	48.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,576.30</b>	<b>5,905.40</b>	<b>16,670.90</b>	<b>73.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>22,576.30</b>	<b>4,700.00</b>	<b>17,876.30</b>	<b>79.18</b>

### INSPECTION

Date of Assignment:	20/07/2020		
Date Inspected:	21/07/2020	Inspected At:	Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Aug 2020)
<b>Parts:</b>	143	MAZDA 6 2.0 SEDAN EXECUTIVE EU6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLT5466J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	2,575.00 FL	*1,115.00 FL
2	1		*BOOTLID LOK	Serviceable	398.00 FL	*- FL
3	1		*BOOTLID LOCK CATCH	Not Necessary	181.00 FL	*- FL
4	1		*BOOTLID WEATHERSTRIP	Twisted	297.00 FL	*135.60 FL
5	2		*BOOTLID HINGE	Not Necessary	620.00 FL	*- FL
6	2		*BOOTLID HINGE GARNISH	Not Necessary	178.00 FL	*- FL
7	1		*BOOTLID MAZDA EMBLEM	Necessary	118.00 FL	*49.20 FL
8	1		*BOOTLID MAZDA 6 EMBLEM	Necessary	106.00 FL	*45.00 FL
9	1		*BOOTLID SKYACTIV EMBLEM	Necessary	119.00 FL	*74.70 FL
10	1		*BOOTLID INNER TRIM	Not Necessary	328.00 FL	*- FL
11	1		*BOOTLID CHROME GARNISH	Not Necessary	455.00 FL	*- FL
12	2		*BOOTLID LICENCE PLATE LAMP	Not Necessary	126.00 FL	*- FL
13	2		*BOOTLID LAMP	Not Necessary	1,218.00 FL	*- FL
14	4		*BOOTLID RUBBER STOPPER	Not Necessary	72.00 FL	*- FL
15	2		*TAILLAMP	Not Necessary	3,346.00 FL	*- FL
16	2		*TAILLAMP WEATHERSEAL	Not Necessary	92.00 FL	*- FL
17	2		*TAILLAMP PANEL	Not Necessary	682.00 FL	*- FL
18	1		*REAR BUMPER UPPER	Dented / Deformed	1,395.00 FL	*1,266.60 FL
19	1		*REAR BUMPER SKIRTING	Deformed / Cracked	1,044.00 FL	*900.00 FL
20	1		*REAR BUMPER DIFFUSER	No such part	558.00 FL	*- FL
21	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	59.00 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINER	Not Necessary	96.00 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Dented	615.00 FL	*538.30 FL
24	2		*REAR BUMPER REFLECTOR	Not Necessary	290.00 FL	*- FL
25	1		*REAR BUMPER CENTER GUIDE	No such part	143.00 FL	*- FL
26	2		*REAR BUMPER SIDE GUIDE	Not Necessary	98.00 FL	*- FL
27	1		*END PANEL	Dented	899.00 FL	*700.10 FL
28	1		*END PANEL TOP GARNISH	Serviceable	223.00 FL	*- FL
29	1		*SPARE WHEEL PANEL	Not Necessary	988.00 FL	*- FL
30	2		*REAR FENDER INNER TRIM	Not Necessary	864.00 FL	*- FL
31	1		*REAR COMPARTMENT TOP BOARD	Not Necessary	328.00 FL	*- FL
32	1		*EXHAUST ASSY	Not Necessary	1,191.00 FL	*- FL
33	2		*EXHAUST ASSY CHROME GARNISH	Not Necessary	990.00 FL	*- FL
34	4		*EXHAUST ASSY MOUNTING	Not Necessary	128.00 FL	*- FL
35	2		*EXHAUST ASSY HEATSHIELD	Not Necessary	236.00 FL	*- FL
36	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	100.00 FS	*- FS
37	4		*BOOTLID HINGE COVER CLIPS	Not Necessary	22.00 FS	*- FS
38	3		*BOOTLID EMBLEM LOGO CLIPS	Not Necessary	16.50 FS	*- FS
39	1		*SET REAR BUMPER CLIPS	Necessary	44.00 FS	*44.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	4		*END PANEL TOP GARNISH CLIPS	Not Necessary	22.00 FS	*- FS
41	12		*REAR FENDER INNER TRIM CLIPS	Not Necessary	66.00 FS	*- FS
42	1		*REAR LICENCE PLATE AND FRAME	Not Necessary	55.00 FS	*- FS
43	8		*BOOTLID INNER TRIM CLIPS	Not Necessary	44.00 FS	*- FS
44	4		*BOOTLID CHROME GARNISH CLIPS	Not Necessary	22.00 FS	*- FS
45	1		*TAILLAMP PANEL SEALANT	Not Necessary	100.00 FS	*- FS
46	1		*END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
47	1		*BOOTLID SPOILER	Not Necessary	500.00 FS	*- FS
48	1		*REVERSE SENSOR (FACTORY ORIGINAL) (4PCS)	Shorted (2Pcs Only)	1,520.00 FS	*361.80 FS
49	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>23,717.50</b>	<b>5,280.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	4,211.20	964.90
<b>Total Parts (\$)</b>	<b>19,506.30</b>	<b>4,315.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,200.00	600.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	20.00
3	TO REMOVE, REFIT BOOTLID COMPONENTS AND REPLACE BOOTLID, CHECK AND RE-ADJUST CLOSE GAP, ALIGNMENT AND WATER SEEPAGE	New	100.00	60.00
4	TO MEASURE, DRILL HOLES ON REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST DISTANCE AND FUNCTIONS	New	100.00	50.00
5	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE EXHAUST SILENCER	New	200.00	0.00
6	TO RESET TAILGATE AUTO LOCK MECHANISM	New	100.00	0.00
7	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY BOOTLID, REAR BUMPER, END PANEL, SPARE WHEEL PANEL AND OTHER AFFECTED AREA / PANEL	New	1,200.00	800.00
8	TO UNDERCOAT ALL AFFECTED PORTIONS AFTER REPAIR	New	120.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>3,070.00</b>	<b>1,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >