

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT120007461/49f3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT5466J

at Workshop m/s Automobile hub

of _____

Insured: _____

Policy No. DMPCSNW00005432000

Claims No. SNM20D202504C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 76k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

x84J

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLT5466J Yr Regn: 101 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: mazda 6 c.c. 1998

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 50189 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6AL107/J0127802

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/402R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/7/20 D.O.I. 21/7/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Reen

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L7A 53586 2079k.

21/8/20 1/5 @ 4700 confirmed with AH Xiang (Red \$17876.30, 79%)

21/08/20@10.59am revised to Tan Kah Leong via Merimen.

Date/Time, File Pass to?

☐

: Preli. Report

1) 21/08 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : MER-TP

Lump Sum ~~4700~~ (\$ 4700)

TOTAL

Repair Estimate

Automobile Hub Enterprise

1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883
Tel: (65) 9786 4483 Fax: (65) 6509 6584 Email: autohub325@gmail.com

Not Authorized
nhr
1/545 H700
21/9/20
Hdang.

Make/Model: MAZDA 6

Engine/Chassis No.: JM6GL1071J0127802

Date of accident:

Damaged area: Rear


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~the~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Date: 20/07/2020

Claim Type: TP

VRN: SLT5466J



"Without Prejudice" basis
No claim shall be made or allowed
Super-Nature 4000 Super Insurance and
from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bootlid 1115 20/Beaf	1	\$ 2,575.00	\$ 2,575.00	
2	Bootlid lock 511	1	\$ 398.00	\$ 398.00	X
3	Bootlid lock catch 11	1	\$ 181.00	\$ 181.00	X
4	Bootlid weatherstrip 135.60 7W1	1	\$ 297.00	\$ 297.00	
5	Bootlid hinge 11	2	\$ 310.00	\$ 620.00	X
6	Bootlid hinge garnish 11	2	\$ 89.00	\$ 178.00	X
7	Bootlid "MAZDA" emblem 49.20 111	1	\$ 118.00	\$ 118.00	
8	Bootlid "MAZDA 6" emblem 45.00 111	1	\$ 106.00	\$ 106.00	
9	Bootlid "SKYACTIV" emblem 74.70 111	1	\$ 119.00	\$ 119.00	
10	Bootlid inner trim 11	1	\$ 328.00	\$ 328.00	X
11	Bootlid chrome garnish 11	1	\$ 455.00	\$ 455.00	X
12	Bootlid licence plate lamp 11	2	\$ 63.00	\$ 126.00	X
13	Bootlid lamp 11	2	\$ 609.00	\$ 1,218.00	X
14	Bootlid rubber stopper 11	4	\$ 18.00	\$ 72.00	X
15	Taillamp 11	2	\$ 1,673.00	\$ 3,346.00	X
16	Taillamp weatherseal 11	2	\$ 46.00	\$ 92.00	X
17	Taillamp panel 11	2	\$ 341.00	\$ 682.00	X
18	Rear bumper upper 1266.60 20/111	1	\$ 1,395.00	\$ 1,395.00	
19	Rear bumper skirting 900 20/111	1	\$ 1,044.00	\$ 1,044.00	
20	Rear bumper diffuser 11	1	\$ 558.00	\$ 558.00	X
21	Rear bumper tow hook cover 11	1	\$ 59.00	\$ 59.00	X
22	Rear bumper side retainer 11	2	\$ 48.00	\$ 96.00	X
23	Rear bumper reinforcement 538.30 20	1	\$ 615.00	\$ 615.00	
24	Rear bumper reflector 11	2	\$ 145.00	\$ 290.00	X
25	Rear bumper center guide 11	1	\$ 143.00	\$ 143.00	X
26	Rear bumper side guide 11	2	\$ 49.00	\$ 98.00	X
27	End panel 700.10 20	1	\$ 899.00	\$ 899.00	
28	End panel top garnish 11	1	\$ 223.00	\$ 223.00	X
29	Spare wheel panel 11	1	\$ 988.00	\$ 988.00	X
30	Rear fender inner trim 11	2	\$ 432.00	\$ 864.00	X
31	Rear compartment top board 11	1	\$ 328.00	\$ 328.00	X
32	Exhaust Assy 11	1	\$ 1,191.00	\$ 1,191.00	X
33	Exhaust Assy chrome garnish 11	2	\$ 495.00	\$ 990.00	X

Repair Estimate

34	Exhaust Assy mounting	11	4	\$ 32.00	\$ 128.00	X
35	Exhaust Assy heatshield	11	2	\$ 118.00	\$ 236.00	X
Subtotal					\$ 21,056.00	
List discount					20.00%	
Total					\$ 16,844.80	

Special nett items

No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Spare wheel panel sealant	11	1	\$ 100.00	\$ 100.00 X
2	Bootlid hinge cover clips	11	4	\$ 5.50	\$ 22.00 X
3	Bootlid emblem logo clips	11	3	\$ 5.50	\$ 16.50 X
4	Rear bumper clips	ref 11	8	\$ 5.50	\$ 44.00 ✓
5	End panel top garnish clips	11	4	\$ 5.50	\$ 22.00 X
6	Rear fender inner trim clips	11	12	\$ 5.50	\$ 66.00 X
7	Rear licence plate and frame	11	1	\$ 55.00	\$ 55.00 X
8	Bootlid inner trim clips	11	8	\$ 5.50	\$ 44.00 X
9	Bootlid chrome garnish clips	11	4	\$ 5.50	\$ 22.00 X
10	Taillamp panel sealant	11	1	\$ 100.00	\$ 100.00 X
11	End panel sealant	11	1	\$ 100.00	\$ 100.00 50
12	Bootlid spoiler	11	1	\$ 500.00	\$ 500.00 X
13	Reverse sensor (Factory Original) 180-90x2	shards	12	\$ 380.00	\$ 1,520.00 361-80 S-N
14	Sundries	11	1	\$ 50.00	\$ 50.00 X
Total					\$ 2,661.50

Labour

No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00	600
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00	20
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00	60
4	To measure, drill holes on replaced rear bumper, position and install reverse sensor, check and test distance and functions.	0.5	\$ 100.00	50
5	To remove and refit, straighten and re-adjust exhaust pipe and replace exhaust silencer.	1	\$ 200.00	11 X
6	To reset tailgate auto lock mechanism.	0.5	\$ 100.00	11 X
7	Supply spray paint material and necessary items to respray bootlid, rear bumper, end panel, spare wheel panel and other affected area / panel.	6	\$ 1,200.00	800
8	To undercoat all affected portions after repair.	1	\$ 120.00	60
Total labour			\$ 3,070.00	

Estimate Grand Total	\$ 22,576.30
----------------------	--------------

P- 4824.50
 22
 7- 3859.60
 S.N- 455.80
 L- 1590.00
 5905.4 4724