

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Aug 2020 Edit Reg		20 Jul 2020 00:00 Edit Adj Rpt	S\$11,000.00 Edit Estimates	S\$11,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	KHO SOON IMM		
Vehicle Reg. No.:	SLA8539M	Date of Loss:	17/07/2020 17:00 - :59 [51 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT20070231	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHB4452Y	Policy No. (Claimant):	SD20V03179
		Excess:	
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/07/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (12/10/2020): **Alert - Adj Mandate Approved (S\$12610.00) - SLA8539M - Claim Handler: Sherini Pi...**
- III_SG (21/07/2020): **Alert - Adj Mandate Approved (S\$0.00) - SLA8539M - Claim Handler: Sherini Pillai**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SLA8539M (MCT20070231)**
[SHB4452Y]
TP
KHO SOON IMM
Jul 17 2020 5:00PM
[COMFORT TRANSPORTATION PTE LTD]
Kah Motor Co Sdn Bhd

View

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/20 18:18	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	23/07/20 18:18	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/07/20 18:18	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	17/08/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/07/20 15:33	ACKNOWLEDGEMENT EMAIL TO III DD 20.07.2020	 Load PDF	
2	20/07/20 15:33	TP ESTIMATE	 Load PDF	
3	20/07/20 15:33	TP GIA REPORT	 Load PDF	
4	21/07/20 08:49	TP VEH DETAILS	 Load PDF	
5	18/08/20 10:37	TP ESTIMATE_MARKED	 Load PDF	
6	06/10/20 16:40	LOD	 Load PDF	
7	06/10/20 16:40	Authorisation to Act	 Load PDF	
8	06/10/20 16:40	Workshop Invoice	 Load PDF	
9	30/10/20 15:40	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/07/20 08:37	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20007464/R1PA3S2
Date: 30/10/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLA8539M	Insured Vehicle No :	SHB4452Y
Date of Loss:	17/07/2020	Nature of Claim:	TP
		Claim No:	MCT20070231

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA8539M	Engine No:	L15Z71001525
Make & Model:	HONDA HR-V, 1.5 LX CVT (A)	Chassis No:	MRHRU1830FP000834
Reg. Date:	18/03/2016 (Man. Year: 2016)	Odometer:	74675 km
Colour:	Maroon		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,060.44	2,524.99	2,535.45	50.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,340.00	8,475.01	6,864.99	44.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,400.44	11,000.00	9,400.44	46.08
+ GST 7.00/7.00% (S\$)	1,428.03	770.00	658.03	46.08
Nett Amount (S\$)	21,828.47	11,770.00	10,058.47	46.08
+ Loss of Use (14.0 x S\$60.00/day) (S\$)		840.00		
	Nett Liability (S\$)	12,610.00		

INSPECTION

Date of Assignment:	20/07/2020		
Date Inspected:	23/07/2020	Inspected At:	Kah Motor Co Sdn Bhd NO. 255 ALEXANDRA ROAD SINGAPORE 159937
Estimated Period of Repair:	12.0 days		

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Oct 2020)	
Parts:	N/A	HONDA HR-V 1.5 LX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA8539M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE COMP	Bent	641.77 FS	*556.20 FS
2	1		*WEATHERSTRIP TAILGATE	Necessary	75.97 FS	*65.84 FS
3	1		*LOCK ASSYTAILGATE	Serviceable	64.65 FS	*- FS
4	1		*SWITCH ASSYTAILGATE OPENER	Serviceable	81.00 FS	*- FS
5	1		*EMBLEMRR.	Necessary	10.95 FS	*9.49 FS
6	1		*EMBLEM,RR. I-VTEC	Necessary	11.92 FS	*10.33 FS
7	1		*GARNISH ASSYRR.LICENCE	Serviceable	142.35 FS	*- FS
8	1		*EMBLEMH	Necessary	8.02 FS	*6.95 FS
9	1		*NUTPUSH 3MM	Necessary	3.15 FS	*2.73 FS
			2pcs			
10	1		*LIGHT ASSY,R.LID	Serviceable	207.67 FS	*- FS
11	1		*LIGHT ASSY,L.LID	Serviceable	207.67 FS	*- FS
12	1		*LAMP UNITR.	Serviceable	361.80 FS	*- FS
13	1		*LAMP UNITL.	Serviceable	361.80 FS	*- FS
14	1		*LINING ASSYTAILGATE LOWER	Serviceable	73.20 FS	*- FS
15	1		*FACERR.BUMPER	Deformed	347.77 FS	*301.40 FS
16	1		*REFLECTOR ASSYR.RR.	Serviceable	128.10 FS	*- FS
17	1		*REFLECTOR ASSYL.RR.	Serviceable	128.10 FS	*- FS
18	1		*FACER.RR.BUMPER CORNER	Repair	68.40 FS	*- FS
19	1		*FACERR.BUMPER CORNER	Repair	68.40 FS	*- FS
20	1		*SPACER.R.RR.BUMPER SIDE	Necessary	12.97 FS	*11.24 FS
21	1		*SPACER,L.RR.BUMPER SIDE	Necessary	12.97 FS	*11.24 FS
22	1		*CLIP, BUMPER	Necessary	13.80 FS	*11.96 FS
			8pcs			
23	1		*PANEL, COMPRR.	Bent	337.57 FS	*292.56 FS
24	1		*LINING ASSYRR.PANEL	Deformed	49.95 FS	*43.29 FS
25	1		*PANEL SETRR.FLOOR	Buckled	414.75 FS	*359.45 FS
26	1		*STIFFENERRR.JACK UP	Necessary	31.95 FS	*27.69 FS
27	4		*ACT RR.SENSOR	Serviceable	320.00 FS	*- FS
28	1		*NUMBER PLATE WITH CASING	Scratched	45.00 FS	*45.00 FS
29	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	14.47 FS	*12.54 FS
30	1		*DAMPERSTD 5X5	Necessary	6.52 FS	*5.65 FS
31	1		*RUBBER CL WINDSHIELD DAMPER	Necessary	14.47 FS	*12.54 FS
32	1		*CAPPIVOT	Necessary	3.75 FS	*3.25 FS
33	1		*FASTENER BW/SHIELD	Necessary	15.90 FS	*13.78 FS
			4pcs			
34	1		*FASTENER B	Necessary	7.95 FS	*6.89 FS
			2pcs			
35	2		*FASTENER AW/SHIELD	Necessary	5.70 FS	*4.94 FS
36	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
37	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
38	1		*WINDSCREEN DAM KIT.	Necessary	100.00 FS	*100.00 FS
39	2		*GROMMET SCREW	Necessary	3.12 FS	*3.12 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*CLIPTAILGATE SPOILER 9pcs	Necessary	14.62 FS	*14.62 FS
41	1		*CROSSMEMBER COMP,RR.FLOOR RR.	Bent	79.82 FS	*79.82 FS
42	1		*BUZZER ASSYSMART	Cracked	40.10 FS	*40.10 FS
43	1		*RPOTECTORL.RR.WHEELARCH	Cracked	111.86 FS	*111.86 FS
44	1		*SENSOR ASSYPARKING	Not Working	58.30 FS	*58.30 FS
45	1		*SENSOR ASSY PARKING T99	Not Working	44.07 FS	*44.07 FS
46	2		*RETAINER PARKING SENSOR	Necessary	88.14 FS	*88.14 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,060.44	2,524.99
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RR. WINDSCREEN.	New	650.00	340.00
2	BODY JOINT SEALANT TAILGATE.	New	150.00	120.00
3	BODY JOINT SEALANT END PANEL.	New	150.00	120.00
4	BODY JOINT SEALANT FLOOR PANEL.	New	150.00	120.00
5	INSPECT RR LIGHTING MECHANISMS PERFORM WATER.	New	180.00	100.00
6	REMOVE & RENEW REVERSE SENSOR.	New	180.00	140.00
7	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &.	New	650.00	325.00
8	RESET VEHICLE SMART ENTRY SYSTEM.	New	560.00	480.00
9	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.	New	560.00	480.00
10	REMOVE & INSTALL REAR COMPARTMENT LININGS.	New	650.00	650.00
11	REMOVE & RENEW RR FLOOR INSULATOR.	New	350.00	350.00
12	CUT & RENEW RR FLOOR PANEL, END PANEL & DAMAGE PART.	New	6,500.00	2,350.01
13	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	New	4,160.00	2,600.00
14	BODY UNDERSIDE COATING.	New	450.00	300.00
			Gross Labour Cost (S\$)	15,340.00
				8,475.01

Report was unsubmitted during this print-out.

< END OF ESTIMATES >