



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2005981
INV Date 01/09/2020
Reference CS/AGI20007465/Ksf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SKX 2495K

Insured Veh. SLG 3982S

Claim No. C10006684

Policy No.

Accident Date 12/07/2020

Inspection Date 20/07/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20007465/Ksf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 01-09-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 3982S	Veh. Inspected	SKX 2495K
Policy No.		Coverage (\$)	0.00
Claim No.	C10006684	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	20/07/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES B180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2462422J370940	Colour	METALLIC PEARL WHITE
Odometer	34710	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	3 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	3 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/07/2020	Inspection Date	20/07/2020
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 2495K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	BENT	2,122.00	2,122.00
1	TAILGATE WEATHERSTRIP	SERVICEABLE	220.00	-
1	TAILGATE CENTRE LOGO	NECESSARY	53.00	53.00
1	TAILGATE "B180" EMBLEM	NECESSARY	89.00	89.00
10	TAILGATE TRIMBOARD CLIPS @\$10.00	NECESSARY	100.00	100.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,083.00	-
1	REAR BUMPER	BUCKLED	1,610.00	1,610.00
1	REAR BUMPER REINFORCEMENT	BENT	524.00	524.00
4	REAR BUMPER SENSOR @\$190.00	SERVICEABLE	760.00	-
6	REAR BUMPER SENSOR SEAL @\$12.00	NECESSARY	72.00	72.00
1	REAR BUMPER STEP CHROME	DENTED	267.00	267.00
15	REAR BUMPER CLIPS @\$9.00	NECESSARY	135.00	135.00
1	REAR BUMPER LOWER SPOILER	DENTED / CUT	170.00	170.00
1	REAR BUMPER LOWER CHROME	SERVICEABLE	225.00	-
	LESS 10% DISCOUNT		-743.00	-514.20
			6,687.00	4,627.80
<u>SPECIAL NETT ITEMS</u>				
1	TAILGATE "C & C" EMBLEM (SN)	NECESSARY	38.00	38.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
			98.00	78.00
<u>LABOUR</u>				
	TO REMOVE AND REFIX REAR WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE AND REFIX REAR BUMPER SENSOR.		100.00	60.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PANEL BEAT AND STRAIGHTEN REAR FLOORBOARD PANEL, REAR CHASSIS FRAME, TO CUT AND WELD REAR END PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME.		1,200.00	480.00
	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS.		1,000.00	500.00

Report Ref No. CS/AGI20007465/Ksf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST PROOFING ON REPAIRED AND REPLACED PANELS.		80.00	30.00
			2,610.00	1,210.00
GRAND TOTAL			9,395.00	5,915.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,750.00

Report Ref No. CS/AGI20007465/Ksf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 2495K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 2495K

RE-INSPECTION

