

ASS. REC. BY:

REF:

AGW 2000 7465/Ksf3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SK X 24 P5K

Yr Regn:

12, 15

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer B180

c.c

1595

Colour

M.P. White

AC: Insured / Std / NI / NA

Sp. Reading

34.710

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 24624 22J 370940

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SIRlm / STD A/Rlm or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

6

mm

L/Bal.

3

mm

L/Bal.

6

mm

D.O.A.

12/7/20

D.O.I.

20/7/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/7

11 Pmp @ 4750/- Confirm

C# 4645.00 Red - 49%?

Date/Time, File Pass to?

31/08/20

1) Typist

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

4,750/- 4/5



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN :

YOUR REF NO : SLG3982S

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AUTO & GENERAL INSURANCE (SINGAPORE) F

ACCIDENT DATE : 12/07/2020

TP VEH REG NO : SLG3982S

ESTIMATE

NO : QUOT202007-000035(00)

DATE : 17/07/2020

POLICY NO : 999995580

VEH REG NO : SKX2495K

MAKE/MODEL : MERCEDES BENZ B180 STYLE
(R16 LED)

CHASSIS NO : WDD2462422J370940

ENGINE NO : 27091030775710

REG. DATE : 2015

Not Authorized
11 Day @
Survey After Paint
4 days

Estimate Repair Cost to Vehicle No : SKX2495K

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Tailgate	1	2,122.00	2,122.00
2 Tailgate weathstrip	1	220.00	220.00
3 Tailgate centre logo	1	53.00	53.00
4 Tailgate 'B180' emblem	1	89.00	89.00
5 Tailgate trimboard clips	10	10.00	100.00
6 Rear end panel	1	1,083.00	1,083.00
7 Rear bumper	1	1,610.00	1,610.00
8 Rear bumper reinforcement	1	524.00	524.00
9 Rear bumper sensor	4	190.00	760.00
10 Rear bumper sensor seal	6	12.00	72.00
11 Rear bumper step chrome	1	267.00	267.00
12 Rear bumper clips	5	9.00	135.00
13 Rear bumper lower spoiler	1	170.00	170.00
14 Rear bumper lower chrome	1	225.00	225.00
			7,430.00
		Less 10%	743.00
			6,687.00
SPECIAL NET			
15 Tailgate 'C & C' emblem	1	38.00	38.00
16 Rear windscreen sealant	1	60.00	60.00
			98.00
LABOUR			
17 To remove and refix rear windscreen glass	1	150.00	150.00
18 To remove and refix rear bumper sensor	1	100.00	100.00
19 To check and rectify wiring system	1	80.00	80.00
20 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00
21 To putty and spray same on affected areas	1	1,000.00	1,000.00
22 To apply rust proofing on repaired and replaced panels	1	80.00	80.00
			2,610.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized

1201
601
201
4801
5001
301



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN :

YOUR REF NO : SLG3982S

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AUTO & GENERAL INSURANCE (SINGAPORE) F REG. DATE : 2015

ACCIDENT DATE : 12/07/2020

TP VEH REG NO : SLG3982S

ESTIMATE

NO : QUOT202007-000035(00)

DATE : 17/07/2020

POLICY NO : 999995580

VEH REG NO : SKX2495K

MAKE/MODEL : MERCEDES BENZ B180 STYLE
(R16 LED)

CHASSIS NO : WDD2462422J370940

ENGINE NO : 27091030775710

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SKX2495K

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 9,395.00
		ADD GST @ 7%	657.65
		GRAND TOTAL	<u>S\$ 10,052.65</u>

SINGAPORE DOLLAR TEN THOUSAND FIFTY-TWO AND CENTS SIXTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE