

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007466/GRA3Q2**Date:** 13/01/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700044468

Claimant
Vehicle No : SBS6008R **Insured Vehicle No :** SLR7509S

Date of Loss: 13/07/2020 Nature of Claim: TP Claim No: 2971833699SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6008R**

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO ABS (A) Engine No: 90292609013992

Reg. Date: 19/05/2011 (Man. Year: 2011) Chassis No: WEB62808323121900

Colour: Green Odometer: 0 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	640.00	640.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	640.00	640.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	44.80	44.80	0.00	0.00
Nett Amount (S\$)	684.80	684.80	0.00	0.00
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 20/07/2020

Date Inspected: 20/07/2020 Inspected At:

Soon Bee Vehicle & Bodywork
Maintenance (HQ)
2 LOYANG WAY SINGAPORE
508776, 10 ANSON ROAD #33-17
INTERBATIONAL PLAZA
SINGAPORE 079909
Singapore 508776

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR COST	New	640.00	640.00
Gross Labour Cost (S\$)			640.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >