

(08/11/13) wef

ASS. REC. BY: Myra

REF:

CS/AG120007470/U+f3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV3347Y
at Workshop m/s Tan Kim

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$72k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LYAS1038

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

91kVeh No: SLV3347Y Yr Regn: 12/17Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: KIA CARRIS c.c. 1600Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 176584 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAH4815VJ7195302Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GAELANDER COMFORTFront: 6 mm Rear: 6 mm

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 16/7/20 D.O.I. 21/7/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Frt, 0/5 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

next 2096122/8/20 confirmed 4/5 @ 6550 with willian

(Red: 8566.21;56%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Add Fee: ☐ : Site Insp (\$)

S + RS, SI

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$) _____)



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AGI Insured's Veh No : SML6191A

Date of Accident : 16 July 2020

Messrs BIS Motoring Pte Ltd

Date : 18 July 2020

Estimate To Repair SLV3347Y - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7195302

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>Deep cut</i>	\$ 576.00
02	8 ps	rear bumper clips @ \$4.50 <i>neu</i>	\$ 36.00
03	1 pc	rear bumper side retainer o/s <i>11</i>	\$ 28.00
04	1 pc	o/s rear fender <i>DD/Bent</i>	\$ 1,223.00
05	1 pc	o/s rear fender inner cowling <i>11</i>	\$ 224.00
06	6 ps	o/s rear fender inner cowling clips @ \$4.50 <i>11</i>	\$ 27.00
07	1 pc	o/s rear fender sticker <i>11</i>	\$ 28.00
08	1 pc	o/s rear door <i>DD/Bent</i>	\$ 1,309.00
09	1 pc	o/s rear door lock <i>11</i>	\$ 229.00
10	1 pc	o/s rear door lock catch <i>11</i>	\$ 55.00
11	2 ps	o/s rear door hinges @ \$65.00 <i>11</i>	\$ 130.00
12	1 pc	o/s rear door checker <i>11</i>	\$ 35.00
13	1 pc	o/s rear door top moulding <i>neu</i>	\$ 85.00
14	1 pc	o/s rear door weatherstrip <i>neu</i>	\$ 105.00
15	1 pc	o/s rear door frame sticker <i>neu</i>	\$ 28.00
16	1 pc	o/s front door <i>DD/Bent</i>	\$ 1,409.00
17	1 pc	o/s front door outer handle <i>11</i>	\$ 187.00
18	1 pc	o/s front door outer handle extension <i>11</i>	\$ 85.00
19	1 pc	o/s front door lock <i>11</i>	\$ 229.00
20	1 pc	o/s front door catch <i>11</i>	\$ 55.00
21	2 ps	o/s front door hinges @ \$65.00 <i>7m</i>	\$ 130.00
22	2 ps	o/s front door checker @ \$35.00 <i>7m</i>	\$ 70.00
23	1 pc	o/s front door power wndow motor <i>shrub</i>	\$ 310.00
24	1 pc	o/s front door power wndow regulator <i>11</i>	\$ 229.00
25	1 pc	o/s front door weatherstrip <i>neu</i>	\$ 105.00
26	1 pc	o/s front door inner trim board <i>neu</i>	\$ 235.00
27	1 pc	o/s front door frame sticker <i>neu</i>	\$ 28.00
28	1 pc	o/s front door top moulding <i>11</i>	\$ 85.00
29	1 pc	o/s front fender <i>Body 761.00</i>	\$ 1,223.00
30	1 pc	o/s front fender wind deflector <i>11</i>	\$ 28.00
31	1 pc	o/s front fender inner cowling <i>Deform 187.00</i>	\$ 224.56
32	6 ps	o/s front fender inner cowling clips @ \$4.50 <i>11</i>	\$ 27.00
33	1 pc	front bumper side retainer right <i>11</i>	\$ 46.00
34	1 pc	o/s side mirror assy <i>11</i>	\$ 652.00
35	1 pc	o/s front wheel bearing with hub <i>11</i>	\$ 467.80
36	1 pc	o/s front knuckle arm <i>11</i>	\$ 314.40
			\$ 10,257.76
		Less 20 %	\$ 2,051.55
			\$ 8,206.21

not Authorized
neu

d/s \$ 6500
21/7/20

Whipch After repair
5 days

lkk

6477



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AGI Insured's Veh No : SML6191A

Date of Accident : 16 July 2020

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 18 July 2020

Estimate To Repair SLV3347Y - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7195302

S/No	Quantity	Description	Amount	
<u>SPECIAL NETT ITEMS</u>				
37	1 pc	o/s front sport wheel rim <i>cur/serf</i>	\$ 750.00	<i>400</i>
38	1 pc	o/s front wheel tyre <i>src</i>	\$ 250.00	<i>X</i>
39	1 pc	o/s rear sport wheel rim <i>cur/serf</i>	\$ 750.00	<i>400</i>
40	1 pc	o/s rear wheel tyre <i>src</i>	\$ 250.00	<i>X</i>
41	1 pc	rocker panel - stone chip <i>nn</i>	\$ 350.00	<i>X</i>
			\$ 2,350.00	
<u>LABOUR & MISC. CHARGES</u>				
01		To transfer of right both door fittings and perform water seepage test.	\$ 260.00	<i>100</i>
02		To replace o/s side mirror.	\$ <i>11</i> 200.00	<i>X</i>
03		To transfer of tyre, rim and on wheel balancing.	\$ <i>11</i> 60.00	<i>X</i>
04		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ <i>11</i> 200.00	<i>X</i>
05		To check steering geometry and computer wheel alignment.	\$ 80.00	<i>60</i>
06		To rust-proofing of the affected areas.	\$ 350.00	<i>100</i>
07		To replace door frame sticker (2 door).	\$ <i>11</i> 60.00	<i>X</i>
08		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ 250.00	<i>50</i>
09		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,500.00	<i>800</i>
10		Putty and spray painting of the affected portion.	\$ 1,600.00	<i>1100</i>
			\$ 4,560.00	
Total			\$ 15,116.21	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			<i>6477</i>	
			<i>20%</i>	
			<i>5181.60</i>	
			<i>800.00</i>	
			<i>11200.00</i>	
			<i>8191.6</i>	
			<i>6553</i>	