

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007471/ERA3Q2
Date: 06/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900116001
Claimant Vehicle No :	SJU4781Z	Insured Vehicle No :	GBE628P
Date of Loss:	17/07/2020	Nature of Claim:	TP
		Claim No:	4020581835SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU4781Z	Engine No:	1NZD429257
Make & Model:	TOYOTA COROLLA, 1.5 X AXIO (A)	Chassis No:	NZE1416121440
Reg. Date:	11/12/2009 (Man. Year: 2009)	Odometer:	308741 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,666.15	5,689.66	1,976.49	25.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,824.00	2,344.00	480.00	17.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,490.15	8,033.66	2,456.49	23.42
Approved Total (Overridden) (S\$)		6,400.00		

(S\$)	10,490.15	6,400.00	4,090.15	38.99
+ GST 7.00/7.00% (S\$)	734.31	448.00	286.31	38.99
Nett Amount (S\$)	11,224.46	6,848.00	4,376.46	38.99
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		31.00		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		7,579.00		

INSPECTION

Date of Assignment: 20/07/2020

Date Inspected: 20/07/2020

Inspected At:

RYDER AUTO PTE LTD
 2 KAKI BUKIT AVE 2
 #02-19/22 KAKI BUKIT AUTOHUB
 SINGAPORE 417921

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	974.40 FL	*974.40 FL
2	1		*BOOTLID LOCK	Bent	291.60 FL	*291.60 FL
3	1		*BOOT LID MOULDING (WHITE)	Broken	287.10 FL	*287.10 FL
4	1		*BOOTLID SEAL	Crushed	174.40 FL	*174.40 FL
5	1		*BOOTLID TRIM	Not Necessary	182.25 FL	*- FL
6	1		*END PANEL LEFT STAY	Bent	108.50 FL	*108.50 FL
7	1		*END PANEL RIGHT STAY	Not Necessary	108.50 FL	*- FL
8	1		*INNER END PANEL TRIM	Crushed	253.50 FL	*253.50 FL
9	1		*L/BOOTLID HINGE	Bent	132.25 FL	*132.25 FL
10	1		*L/BOOT TRIM COVER	Not Necessary	323.20 FL	*- FL
11	1		*L/CLIP	Necessary	36.00 FL	*36.00 FL
12	1		*L/NO PLATE LAMP BULB	Not Necessary	5.00 FL	*- FL
13	1		*L/R BUMPER BRACKET	Broken	81.35 FL	*81.35 FL
14	1		*L/R OUTER LAMP	Broken	439.10 FL	*439.10 FL
15	1		*L/R SIDE PANEL	Dented	1,336.80 FL	*1,336.80 FL
16	1		*L/R UPP BUMPER BRKT	Broken	71.00 FL	*71.00 FL
17	1		*L/R VENT INSERT	Not Necessary	95.60 FL	*- FL
18	1		*L/R WHEELHOUSE COVER	Cut	163.80 FL	*163.80 FL
19	1		*L/TAILLAMP PANEL	Bent	363.80 FL	*363.80 FL
20	1		*LEFT FLOOR PANEL	Not Necessary	193.80 FL	*- FL
21	1		*LUGG COMPART CARPET	Crushed	561.60 FL	*561.60 FL
22	1		*NUT (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*R/BOOTLID HINGE	Bent	132.25 FL	*132.25 FL
24	1		*R/NUMBER PLATE LAMP	Not Necessary	83.75 FL	*- FL
25	1		*R/R BUMPER BRACKET	Not Necessary	81.35 FL	*- FL
26	1		*R/R OUTER LAMP	Not Necessary	439.10 FL	*- FL
27	1		*R/R UPP BUMPER BRKT	Not Necessary	71.00 FL	*- FL
28	1		*REAR BUMPER	Broken	681.40 FL	*681.40 FL
29	1		*REAR LOCK CATCH	Not Necessary	43.10 FL	*- FL
30	1		*REAR MANUFACT BADGE	Necessary	61.50 FL	*61.50 FL
31	1		*REAR NO PLATE REINF	Not Necessary	29.00 FL	*- FL
32	1		*REAR NUMBER PLATE	Not Necessary	45.00 FL	*- FL
33	1		*REAR PANEL	Dented	881.90 FL	*881.90 FL
34	1		*REAR SCREEN BOND KIT	Necessary	140.00 FL	*140.00 FL
35	1		*REAR SCREEN SEAL	Necessary	60.00 FL	*60.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR SPACER (NPA)	Not Necessary	0.00 FL	*- FL
37	1		*REAR SPACER (NPA)	Not Necessary	0.00 FL	*- FL
38	1		*RR MANUFACTURE BADGE	Necessary	61.70 FL	*61.70 FL
39	1		*SCREW	Necessary	16.00 FL	*16.00 FL
40	1		*BUMPER CLIPS REAR	Necessary	30.00 FS	*30.00 FS
41	1		*BUMPER SCREW REAR	Not Necessary	20.00 FS	*- FS
42	1		*REVERSE SENSOR REAR	Not Necessary	380.00 FS	*- FS
43	1		*REVERSE CAMERA REAR	Not Necessary	280.00 FS	*- FS
44	1		*TRD EMBLEM REAR	Necessary	87.70 FS	*87.70 FS
45	1		*X EMBLEM REAR	Necessary	59.50 FS	*59.50 FS
46	1		*BOOTLID TRIM CLIPS REAR	Necessary	33.00 FS	*20.00 FS
47	1		*WHEELHOUSE CLIPS L/R COVER	Necessary	18.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,918.80	7,517.15
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,252.65	1,827.49
Total Parts (\$\$)	7,666.15	5,689.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL OF LABOUR.	New	1,896.00	1,416.00
2	TOTAL PAINT INCLUDING MATERIAL.	New	928.00	928.00
Gross Labour Cost (S\$)			2,824.00	2,344.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >