

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007477/KPA3Q2

Date: 10/04/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100453598
Claimant Vehicle No :	EY5885P	Insured Vehicle No :	SDD7100E
Date of Loss:	16/07/2020	Nature of Claim:	TP
		Claim No:	6540993807SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EY5885P	Engine No:	G4FGHH686959
Make & Model:	KIA CERATO, 1.6 SUNROOF (A)	Chassis No:	KNAFZ411MJ5754317
Reg. Date:	30/11/2017 (Man. Year: 2017)	Odometer:	46725 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 2 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,923.26	0.00	2,923.26	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	410.00	830.00	66.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,163.26</b>	<b>410.00</b>	<b>3,753.26</b>	<b>90.15</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>291.43</b>	<b>28.70</b>	<b>262.73</b>	<b>90.15</b>
<b>Nett Amount (S\$)</b>	<b>4,454.69</b>	<b>438.70</b>	<b>4,015.99</b>	<b>90.15</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 20/07/2020

Date Inspected: 22/07/2020 Inspected At:

Ah Lim Motor Company (AMK)  
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK  
Autopoint  
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Serviceable	2,368.70 FL	*- FL
2	1		*FRONT BUMPER	Repair	633.60 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	9.66 FL	*- FL
4	12		*FRONT BUMPER CLIPS	Not Necessary	24.00 FL	*- FL
5	1		*FRONT BUMPER LOWER GARNISH	Repair	81.42 FL	*- FL
6	1		*FRONT BUMPER GRILLE RH	Serviceable	29.29 FL	*- FL
7	1		*FRONT FENDER COWLING RH	Not Necessary	85.40 FL	*- FL
8	8		*FRONT FENDER COWLING CLIPS	Not Necessary	16.00 FL	*- FL
9	1		*SPORT RIM RHF (NPA)	Serviceable	0.00 FS	*- FS
10	1		*TYRE RHF (NPA)	Serviceable	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,248.07	0.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	324.81	0.00
Total Parts (\$\$)	2,923.26	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC ,TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTION	New	40.00	10.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	0.00
3	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSOR	New	60.00	0.00
4	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
5	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD ,TO KNOCK & REPAIR FRONT FENDER RH ,FRT INNER PANELS INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	400.00	100.00
6	TO SPRAY FRONT BUMPER FRONT BUMPER LOWER GARNISH FRONT FENDER	New	600.00	300.00
<b>Gross Labour Cost (S\$)</b>			<b>1,240.00</b>	<b>410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >