

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20007480/QVF3E2  
**Date:** 27/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100169700-10	
<b>Claimant Vehicle No :</b> SLJ1168Z	<b>Insured Vehicle No :</b> SJT6152G	
Date of Loss: 18/07/2020	Nature of Claim: TP	Claim No: 3833144454SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ1168Z		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZR1833642
Reg. Date:	10/10/2016 (Man. Year: 2016)	Chassis No:	JTDGG20W90J005167
Colour:	White	Odometer:	84042 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sumitomo 6 mm	Rear Left Side:	Sumitomo 6 mm
Front Right Side:	Sumitomo 6 mm	Rear Right Side:	Sumitomo 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	20/07/2020	
Date Inspected:	21/07/2020 Inspected At:	Seng Hwee Motor (HQ) Blk 1018 Yishun Industrial Park A #01-350 Singapore 768760
Estimated Period of Repair:	3.0 days	

**Adjuster:** OI SUN PIN

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER LH	Broken	0.00 F	*- F
4	1		*FRT LH BUMPER FOG LAMP COVER CHROME	Scratched	0.00 F	*- F
5	1		*FRT LH HEADLAMP ASSY	Scratched	0.00 F	*- F
6	1		*FRT LH FENDER	Repair	0.00 F	*- F
7	1		*FRT LH FENDER INNER SHIELD	Cut	0.00 F	*- F
					<b>Total Parts (\$\$)</b>	<b>0.00 0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**