

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 288K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, FR BUMPER (DISC 25%)	DENTED	521.00	390.75
10	CLIPS PIECE, FRT & RR BUMPER @\$4.50 (DISC 25%)	NECESSARY	45.00	33.75
1	UNIT, HEADLAMP, RH (DISC 10%)	SCRATCHED	2,637.60	2,373.84
1	SUPPORT, FR BUMPER RH	SERVICEABLE	80.10	-
1	GRILLE, RADIATOR	SERVICEABLE	178.60	-
1	MOULDING, FRONT BUMPER SIDE, RH	SERVICEABLE	95.60	-
1	ABSORBER, FR BUMPER	SERVICEABLE	80.20	-
1	REINFORCEMENT FRONT UPPER	SERVICEABLE	716.60	-
1	ABSORBER, FR BUMPER LOWER	SERVICEABLE	132.70	-
1	EXTENSION SUB-ASSY, RH	SERVICEABLE	120.10	-
1	REINFORCEMENT FRONT LOWER	SERVICEABLE	246.10	-
1	COVER ASSY, ENGINE	SERVICEABLE	241.90	-
1	SUPPORT, RADIATOR UPPER RH	SERVICEABLE	78.90	-
1	LINER, FR FENDER, RH	SERVICEABLE	202.50	-
			5,376.90	2,798.34
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK.		676.00	200.00
	SPRAY PAINT.		558.00	200.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	
			1,574.00	420.00
	GRAND TOTAL		6,950.90	3,218.34

|--|

Report Ref No. NS/INC20007490/Qvf3e2

Jas

OI SUN PIN

Asst. Automotive Assessor

7

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser