



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

INV No. AC2005934  
INV Date 28/08/2020  
Reference CS/AGI20007506/Uvf3n2  
Code AGI



### PROFESSIONAL SERVICE FEE

Vehicle No. SKD 759T

Insured Veh. SFU 6252T

Claim No. C10006777

Policy No.

Accident Date 20/07/2020

Inspection Date 21/07/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>450.00</b>
<b>GST (7%)</b>	<b>31.50</b>
<b>Grand Total</b>	<b>481.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

**LKK Auto Consultants Pte Ltd**

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20007506/Uvf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 28-08-2020



Code : AGI

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SFU 6252T	<b>Veh. Inspected</b>	SKD 759T
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10006777	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVY RATILLA	<b>Assign Date</b>	21/07/2020

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ E 200 (A)	<b>c.c</b>	1796
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2011
<b>Chassis No.</b>	WDD2120482A506688	<b>Colour</b>	BLACK
<b>Odometer</b>	147250	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	245/35 ZR19	TOYO	6 mm
<b>L/H Front Tyre</b>	245/35 ZR19	TOYO	6 mm
<b>R/H Rear Tyre</b>	275/30 ZR19	FALKEN	6 mm
<b>L/H Rear Tyre</b>	275/30 ZR19	FALKEN	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

#### 5. General Information

<b>Accident Date</b>	20/07/2020	<b>Inspection Date</b>	21/07/2020
<b>Survey held at</b>	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 759T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BOOTLID (N)	TO REPAIR SEE LABOUR	3,018.00	-
1	BOOTLID REAR LOGO (N)	NECESSARY	105.00	95.00
1	BOOTLID 7-G TRONIC EMBLEM (N)	NECESSARY	102.00	82.00
1	BOOTLID "E200" EMBLEM (N)	NECESSARY	82.00	82.00
1	BOOTLID C&C LOGO (N)	NECESSARY	68.00	68.00
1	BOOTLID CHROME MOULDING (N)	NOT NECESSARY	194.00	-
1	BOOTLID INNER LOCK (N)	TWISTED	280.00	280.00
1	BOOTLID LOCK PUMP (N)	NOT NECESSARY	650.00	-
1	BOOTLID LOCK STRIKER (N)	NOT NECESSARY	62.00	-
1	BOOTLID WEATHERSTRIP (N)	TWISTED	292.00	292.00
2	BOOTLID STOPPER @\$8.00 (N)	NOT NECESSARY	16.00	-
1	BOOTLID INNER HANDLE (N)	NOT NECESSARY	53.00	-
2	BOOTLID REFLECTORS @\$485.00 (N)	NOT NECESSARY	970.00	-
1	BOOTLID INNER TRIM BOARD (N)	NOT NECESSARY	215.00	-
1	REAR BUMPER (N)	DISTORTED	1,658.00	1,415.32
1	REAR BUMPER CENTRE CHROME MOULDING (N)	NECESSARY	185.00	185.00
2	REAR BUMPER SIDE CHROME MOULDINGS @\$171.00 (N)	NECESSARY	342.00	262.00
1	REAR BUMPER CENTRE GARNISH (N)	DEFORMED / TORN	660.00	345.00
2	REAR BUMPER SIDE RETAINERS @\$36.00 (N)	NOT NECESSARY	72.00	-
1	REAR BUMPER INNER RETAINER (N)	CRACKED	168.00	168.00
2	REAR BUMPER LOWER BRACKETS @\$20.00 (N)	CRACKED	40.00	40.00
1	REAR BUMPER REINFORCEMENT (N)	BENT	655.00	655.00
2	HEADRESTS @\$915.00 (N)	TO REPAIR SEE LABOUR	1,830.00	-
1	REAR END PANEL (N)	BADLY DENTED	1,415.00	1,245.35
1	REAR END PANEL TOP GARNISH (N)	TWISTED	426.00	361.00
2	TAILLAMPS @\$1260.00 (N)	CRACKED	2,520.00	1,290.00
2	TAILLAMPS HOUSING PANELS @\$150.00 (N)	TO REPAIR SEE LABOUR	300.00	-
2	REAR FENDERS @\$1600.00 (N)	TO REPAIR SEE LABOUR	3,200.00	-

Report Ref No. CS/AGI20007506/Uvf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIMS @\$212.00 (N)	NOT NECESSARY	424.00	-
1	REAR SPARE TYRE TOP BOARD (N)	NOT NECESSARY	889.00	-
1	REAR SPARE TYRE BOARD (FIBRE)(N)	CRACKED	415.00	415.00
1	REAR FLOOR PANEL (N)	TO REPAIR SEE LABOUR	1,310.00	-
4	REAR PDC SENSORS @\$265.00 (N)	SHORTED (2 PCS ONLY)	1,060.00	450.00
	LESS 10% DISCOUNT		-	-773.07
			23,676.00	6,957.60
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BOOTLID C&C LOGO (SN)	REPEATED	45.00	-
1	REAR LICENSE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
2	REAR EXHAUST CHROME @\$250.00 (SN)	SERVICEABLE	500.00	-
			695.00	50.00
	<b><u>LABOUR</u></b>			
	TO RESET AND REPROGRAMME HEADREST.		120.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TO DISMENTLE & REPLACING REVERSE SENSOR.		100.00	50.00
	TO TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	180.00	-
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY.		180.00	80.00
	TO DISMENTLE & REPLACING REAR EXHAUST.	NOT NECESSARY	180.00	-
	TO SPRAY ANTI RUST PROOFING.		150.00	50.00
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REPLACING PARTS.		1,000.00	900.00
	INCLUSIVE OF THE REPAIR OF BOOTLID,HEADRESTS,TAILLAMPS HOUSING PANELS,REAR FENDERS AND REAR FLOOR PANEL.			
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			3,510.00	2,190.00
<b>GRAND TOTAL</b>			<b>27,881.00</b>	<b>9,197.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,300.00</b>

Report Ref No. CS/AGI20007506/Uvf3n2



Report Ref No. CS/AGI20007506/Uvf3n2

A handwritten signature in black ink, appearing to be 'Chua' followed by a stylized 'K' and 'S'.

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**