

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20007507/AVF3E2

Date: 04/11/2020

REFERENCE

| | |
|--|--|
| Insured/Claimant: PNG JIALING KIM (FANG JIALING KIM) | Policy No: 1900106588 |
| Date of Loss: 20/07/2020 | Nature of Claim: OD Claim No: 7558066107SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | |
|---|-------------------------------|
| Reg No: SMM1249X | Engine No: CHZC30378 |
| Make & Model: AUDI A3, 999cc SEDAN TFSI (A) | Chassis No: WAUZZZ8V9KA084718 |
| Reg. Date: 18/06/2019 (Man. Year: 2019) | Odometer: 8645 km |
| Colour: Grey | |
| Engine Capacity: 999 cc | |
| Market Value/New Car Price: S\$95,000.00 | |
| Sum Insured (\$\$): Market Value/New Car Price | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | |
|------------------------------------|-----------------------------------|
| Front Tyre Size: 205/55 R16 | Rear Tyre Size: 205/55 R16 |
| Front Left Side: Bridgestone 6 mm | Rear Left Side: Bridgestone 6 mm |
| Front Right Side: Bridgestone 6 mm | Rear Right Side: Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 11,461.60 | 8,172.00 | 3,289.60 | 28.70 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,272.00 | 3,722.00 | 2,550.00 | 40.66 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 17,733.60 | 11,894.00 | 5,839.60 | 32.93 |
| - Excess (\$\$) | 600.00 | 600.00 | 0.00 | 0.00 |
| (\$\$) | 17,133.60 | 11,294.00 | 5,839.60 | 34.08 |
| + GST 7.00/7.00% (\$\$) | 1,199.35 | 790.58 | 408.77 | 34.08 |
| Nett Amount (\$\$) | 18,332.95 | 12,084.58 | 6,248.37 | 34.08 |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 21/07/2020 | |
| Date Inspected: | 21/07/2020 | Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 1,987.00 FS | *1,589.60 FS |
| 2 | 1 | | *FRONT BUMPER FIXING PARTS | Not Necessary | 185.00 FS | *- FS |
| 3 | 1 | | *FRONT BUMPER GUIDE SECTION - RH | Damaged | 38.00 FS | *30.16 FS |
| 4 | 1 | | *FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | Torn | 530.00 FS | *424.00 FS |
| 5 | 1 | | *FRONT BUMPER CLOSING ELEMENT - RH | Not Necessary | 293.00 FS | *- FS |
| 6 | 1 | | *FRONT BUMPER COVER TRIM - RH | Cut | 161.00 FS | *128.40 FS |
| 7 | 1 | | *WHEEL HOUSING LINER ADAPTER - RH | Not Necessary | 37.00 FS | *- FS |
| 8 | 1 | | *FRONT BUMPER AIR GUIDE GRILLE - RH | Not Necessary | 186.00 FS | *- FS |
| 9 | 1 | | *FRONT FENDER - RH | Distorted | 841.00 FS | *672.80 FS |
| 10 | 1 | | *FRONT FENDER ATTACHMENT PARTS | Not Necessary | 71.00 FS | *- FS |
| 11 | 1 | | *FRONT FENDER BRACKET - RH | Bent | 38.00 FS | *30.40 FS |
| 12 | 1 | | *FRONT FENDER BRACE | Bent | 95.00 FS | *75.68 FS |
| 13 | 1 | | *WHEEL HOUSING LINER - RH | Deformed | 167.00 FS | *133.20 FS |
| 14 | 1 | | *WHEEL HOUSING LINER ATTACHMENT PARTS | Not Necessary | 88.00 FS | *- FS |
| 15 | 1 | | *LED HEADLIGHT - RH | Cracked | 5,455.00 FS | *4,364.00 FS |
| 16 | 1 | | *LIFT CYLINDER - RH | Not Necessary | 141.00 FS | *- FS |
| 17 | 1 | | *FRONT ALUMINIUM RIM - RH | Cut | 699.00 FS | *558.80 FS |
| 18 | 1 | | *SUNDRIES | Necessary | 300.00 FS | *15.36 FS |
| 19 | 1 | | *FRONT BUMPER FOAM FILLER PIECE | Torn | 149.60 FS | *149.60 FS |

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,461.60 8,172.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE | New | 350.00 | 250.00 |
| 2 | TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY | New | 350.00 | 350.00 |
| 3 | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 2,100.00 | 1,000.00 |
| 4 | TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR | New | 3,000.00 | 1,650.00 |
| 5 | TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT | New | 280.00 | 280.00 |
| 6 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (\$\$) | | | 6,272.00 | 3,722.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >