

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007509/T1RS3Q2
Date: 03/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900249295
Claimant Vehicle No :	SHC2510X	Insured Vehicle No :	SMR77E
Date of Loss:	20/07/2020	Nature of Claim:	TP
		Claim No:	3252162138SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2510X		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU668499
Reg. Date:	25/01/2017 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU098568
Colour:	Blue	Odometer:	37589 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,907.84	1,083.28	1,824.56	62.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,270.00	610.00	32.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,787.84	2,353.28	2,434.56	50.85
Approved Total (Overridden) (S\$)		1,900.00		
	(S\$)	4,787.84	1,900.00	2,887.84
	+ GST 7.00/7.00% (S\$)	335.15	133.00	202.15
	Nett Amount (S\$)	5,122.99	2,033.00	3,089.99
	+ Car Rental (3.0 x S\$112.67/day) (S\$)		338.01	
	+ Doc/Search Fee (S\$)		7.49	
	Nett Liability (S\$)		2,378.50	

INSPECTION

Date of Assignment:	21/07/2020		
Date Inspected:	21/07/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ASSY -RR BUMPE	Deformed	1,106.00 FL	*1,106.00 FL
2	1		*BRKT ASSY -RR BUMPER	Necessary	35.60 FL	*35.60 FL
3	1		*PANEL ASSY-QUARTER	Repair	2,171.40 FL	*- FL
4	1		*MOULDING-RR WDO GLA	Not Necessary	51.80 FL	*- FL
5	2		*(ALL) WINDSCREEN AHESIVE -3	Not Necessary	46.00 FS	*- FS
6	1		*APP LOGO REAR DOOR L/R CT	Necessary	80.00 FS	*80.00 FS
7	1		*CAP ASSY -WHEEL HUB	Cut	112.50 FL	*112.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,603.30	1,334.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	695.46	250.82
Total Parts (\$\$)	2,907.84	1,083.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	850.00	560.00
2	SPRAYPAINT ON AFFECTED AREA	New	650.00	600.00
3	TUFF COAT ON AFFECTED PARTS	New	30.00	30.00
4	REMOVE/REFIX RR W/SCREEN TO ASST R/P	New	120.00	0.00
5	REMOVE/REFIX UPHOLSTERY ASST REPAIR	New	150.00	0.00
6	ADJUST FRONT WHEEL ALIGNMENT	New	80.00	80.00
Gross Labour Cost (S\$)			1,880.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >