



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 6310K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	AIR CLEANER TANK	CRACKED	939.87	939.87
1	REAR DIESEL TANK	BENT	1,112.60	1,011.50
1	CABIN REAR MUDFLAP GARNISH	SCRATCHED	187.90	187.90
1	REAR SIDE BOARD - RH	TO REPAIR SEE LABOUR	1,100.00	-
1	REAR SIDE BOARD CROSS MEMBER	TO REPAIR SEE LABOUR	650.00	-
1	REAR SIDE BOARD STOPPER	MISSING	68.60	68.60
	LESS 20% DISCOUNT		-811.79	-
	LESS 25% DISCOUNT		-	-551.97
			3,247.18	1,655.90
	<b><u>LABOUR</u></b>			
	LABOUR TO SPRAY PAINT.		500.00	300.00
	LABOUR TO PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR SIDE BOARD - RH AND REAR SIDE BOARD CROSS MEMBER.		400.00	400.00
			900.00	700.00
	<b>GRAND TOTAL</b>		<b>4,147.18</b>	<b>2,355.90</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,900.00</b>

Report Ref No. CS/FCI20007510/Qtf3s2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.