

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007511/UPA3Q2

Date: 30/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMM1545R

Insured Vehicle No : SGQ4577D

Date of Loss: 16/07/2020

Nature of Claim: TP

Claim No: 0756134520SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM1545R

Make &amp; Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)

Engine No: HRA2286640A

Reg. Date: 21/06/2016 (Man. Year: 2016)

Chassis No: SJNFEAJ11U1677239

Colour: White

Odometer: 106996 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's      | Adjuster's      | Difference      | Diff %       |
|---|-----------------|-----------------|-----------------|--------------|
| Parts   | 2,202.66        | 1,565.84        | 636.82          | 28.91        |
| Miscellaneous Items                             | 0.00            | 0.00            | 0.00            |              |
| Labour  | 1,240.00        | 750.00          | 490.00          | 39.52        |
| Paintwork Labour                                | 0.00            | 0.00            | 0.00            |              |
| Towing  | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>3,442.66</b> | <b>2,315.84</b> | <b>1,126.82</b> | <b>32.73</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                 | <b>1,850.00</b> |                 |              |
| (S\$)   | 3,442.66        | 1,850.00        | 1,592.66        | 46.26        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 240.99          | 129.50          | 111.49          | 46.26        |
| <b>Nett Amount (S\$)</b>                        | <b>3,683.65</b> | <b>1,979.50</b> | <b>1,704.15</b> | <b>46.26</b> |
| <b>+ Loss of Use (3.0 x S\$80.00/day) (S\$)</b> |                 | 240.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>2,221.50</b> |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                 | <b>2,200.00</b> |                 |              |

### INSPECTION

Date of Assignment: 21/07/2020

Date Inspected: 21/07/2020

Inspected At:

Tan Lim Motor Pte Ltd (Defu)

1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 2.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's | Amount     |
|-----|-----|----------|---------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                    | Deformed      | 717.00 FN  | *717.00 FN |
| 2   | 10  |          | *REAR BUMPER CLIPS              | Necessary     | 50.00 FN   | *35.00 FN  |
| 3   | 2   |          | *REAR BUMPER SIDE RETAINER      | Not Necessary | 76.00 FN   | *- FN      |
| 4   | 2   |          | *REAR BUMPER REFLECTOR          | Not Necessary | 132.00 FN  | *- FN      |
| 5   | 1   |          | *REAR BUMPER LOWER BRACKET      | Not Necessary | 176.80 FN  | *- FN      |
| 6   | 1   |          | *SET REAR BUMPER PARKING SENSOR | Shorted       | 477.00 FS  | *200.00 FS |
| 7   | 1   |          | *REAR BUMPER REINFORCEMENT      | Dented / Bent | 619.20 FN  | *619.20 FN |
| 8   | 1   |          | *REAR BUMPER SPONGE             | Torn          | 146.40 FN  | *146.40 FN |

F=Franchise part. S=SpcNett. N=NettItemDisc.

|   |          |          |
|---|----------|----------|
| Sub Total (\$\$)                                    | 2,394.40 | 1,717.60 |
| - Nett Item Discount on N Items 10.00/10.00% (\$\$) | 191.74   | 151.76   |
| Total Parts (\$\$)                                  | 2,202.66 | 1,565.84 |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No                      | Particulars  | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|--------|
| <b>Labour Items</b>     |  |          |            |        |
| 1                       | TO CHECK ELECTRICAL LIGHTING CONCERNED   | New      | 60.00      | 0.00   |
| 2                       | TO REINSTALL OF REAR BUMPER PARKING SENSOR   | New      | 80.00      | 50.00  |
| 3                       | PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New      | 600.00     | 300.00 |
| 4                       | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION   | New      | 500.00     | 400.00 |
| Gross Labour Cost (S\$) |  |          | 1,240.00   | 750.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >