



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2007088  
INV Date 19/10/2020  
Reference CC6/CTI20007512/Kks3q2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SJZ 7866S  
Insured Veh. SLK 6593R  
Claim No. SNM20D202513  
Policy No. DMPCSNW00006332001  
Accident Date 20/07/2020  
Inspection Date 21/07/2020

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI20007512/Kks3q2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 19-10-2020		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLK 6593R	Veh. Inspected	SJZ 7866S	
Policy No.	DMPCSNW00006332001	Coverage (\$)	0.00	
Claim No.	SNM20D202513	Excess (\$)	0.00	
Assign From		Assign Date	21/07/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053ZEE106167901	Colour	WHITE	
Odometer	230433	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WANLI	7 mm	
L/H Front Tyre	195/65 R15	WANLI	7 mm	
R/H Rear Tyre	195/65 R15	FALKEN	5 mm	
L/H Rear Tyre	195/65 R15	FALKEN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/07/2020	Inspection Date	21/07/2020	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 7866S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	TAILGATE	BUCKLED	597.50	597.50
1	TAILGATE LOCK	DENTED	96.50	96.50
1	TAILGATE -ALTIS EMBLEM	NECESSARY	44.10	44.10
1	TAILGATE -COROLLA EMBLEM	NECESSARY	42.30	42.30
1	TAILGATE 1.6 EMBLEM	NECESSARY	32.80	32.80
1	TAILGATE ELEGANCE EMBLEM	NECESSARY	42.20	42.20
1	REAR BUMPER	BUCKLED / CRACKED	459.70	459.70
1	REAR BUMPER SPONGE	CRACKED	117.50	117.50
1	TAILLAMP ,RH	CRACKED	409.90	409.90
1	END PANEL	TO REPAIR SEE LABOUR	248.20	-
1	END PANEL TOP GARNISH	SERVICEABLE	552.10	-
1	REAR BUMPER RETAINER -LONG ,RH	DISTORTED	66.70	66.70
1	REAR BUMPER RETAINER -SMALL ,RH	DISTORTED	29.20	29.20
	LESS 25% DISCOUNT		-684.68	-484.60
			2,054.02	1,453.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE SENSOR (SN)	SCRATCHED	220.00	200.00
			220.00	200.00
	<b><u>LABOUR</u></b>			
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS REPAIR /RESHAPE DAMAGED FENDER CUT N WELD DAMAGED PANEL REPLACE /ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF END PANEL .		800.00	500.00
	PAINTING -TAILGATE ,REAR BUMPER ,REAR FENDER ,RH .		750.00	680.00
			1,550.00	1,180.00
	<b>GRAND TOTAL</b>		<b>3,824.02</b>	<b>2,833.80</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,250.00</b>

Report Ref No. CC6/CTI20007512/Kks3q2



Report Ref No. CC6/CTI20007512/Kks3q2

A handwritten signature in black ink, appearing to read 'KSC'.

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJZ 7866S

INSPECTION





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

