

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

*Not Authorised
1/Rmp @ 2250/-
Resurvey After Paint 4 days*

21, JUL 2020

China Taiping Insurance (S) PL
105 Cecil Street #18-00 The Octagon
S 63896138

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no; SLK6593R
Accident involving vehicle no: SJZ7866S/SLK6593R
DOA: 20/07/2020 AT Junction of Cross Street/Robinson Rd

Dear officer incharge
Re; Estimate cost of repair for vehicle no: SJZ7866S
To supply--

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Description	Qty		Amount -
Tailgate	1	<i>Bur</i>	597.50 —
Tailgate lock	1	<i>Red</i>	96.50 —
Tailgate-Altis emblem	1	<i>Red</i>	44.10 —
Tailgate-corolla emblem	1	<i>Red</i>	42.30 —
Tailgate-1.6 emblem	1	<i>Red</i>	32.80 —
Tailgate Elegance emblem	1	<i>Red</i>	42.20 —
Rear bumper	1	<i>Bur 1cm</i>	459.70 —
Rear bumper sponge	1	<i>CM</i>	117.50 —
Taillamp, Rh	1	<i>CM</i>	409.90 —
End panel	1	<i>R</i>	248.20 X
End panel top garnish	1	<i>Sm</i>	552.10 X
Rear bumper retainer-long, Rh	1	<i>D17</i>	66.70 —
Rear bumper retainer-small, Rh	1	<i>D17</i>	29.20 —
Parts			2,738.70
Parts less 25%			684.68
			2,054.03

Reverse sensor
To remove damaged parts and attachments
Repair/reshape damaged fender
Cut n weld damaged panel
Replace/align all parts into position
Painting-tailgate, rear bumper, rear fender, Rh

Sen 220.00 200sm

800.00 *500l*
750.00 *680l*

2,824.03