

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007513/UPS3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800036037	
Claimant Vehicle No : SJJ90T	Insured Vehicle No : SLX7373J	
Date of Loss: 16/07/2020	Nature of Claim: TP	Claim No: 1361627562SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ90T		
Make & Model: BMW M3, CABRIOLET SMG II	Engine No: 20354375S65B40A	
Reg. Date: 14/11/2008 (Man. Year: 2008)	Chassis No: WBSWL92020P371129	
Colour: Grey	Odometer: 116033 km	
Engine Capacity: 3999 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/50Z R19	Rear Tyre Size: 305/30Z R19	
Front Left Side: Michelin 6 mm	Rear Left Side: Michelin 6 mm	
Front Right Side: Michelin 6 mm	Rear Right Side: Michelin 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,268.55	4,436.50	6,832.05	60.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	870.00	3,230.00	78.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,368.55	5,306.50	10,062.05	65.47
Approved Total (Overridden) (\$\$)		4,200.00		
Nett Amount (\$\$)	15,368.55	4,200.00	11,168.55	72.67
+ Car Rental (4.0 x S\$150.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		29.00		
Nett Liability (\$\$)		4,829.00		

INSPECTION

Date of Assignment: 21/07/2020		
Date Inspected: 22/07/2020	Inspected At:	Zoom Autowerks Pte Ltd 832 SIMS AVENUE #12-884 EUNOSVILLE Singapore 400832
Estimated Period of Repair: 3.0 days		

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (M3)	Deformed /Torn	2,480.00 FL	*1,650.00 FL
2	1		*FRONT BUMPER CENTRE AIR-GRILLE	Not Necessary	586.00 FL	*- FL
3	1		*FRONT BUMPER LH GRILLE	Not Necessary	365.00 FL	*- FL
4	1		*FRONT BUMPER LH HEADLAMP NOZZLE GARNISH	Missing	150.00 FL	*45.00 FL
5	1		*FRONT BUMPER LH HEADLAMP NOZZLE	Cracked	297.00 FL	*297.00 FL
6	2		*FRONT BUMPER SENSOR	Not Necessary	950.00 FL	*- FL
7	4		*FRONT BUMPER SENSOR HOLDER	Not Necessary	112.00 FL	*- FL
8	4		*FRONT BUMPER SENSOR HOLDER RING	Not Necessary	36.00 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Cracked	168.00 FL	*168.00 FL
10	1		*FRONT BUMPER LEFT CORNER MOUNT	Not Necessary	148.00 FL	*- FL
11	1		*FRONT BUMPER TOP CARRIER	Not Necessary	397.00 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Repair	586.00 FL	*- FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FL	*60.00 FL
14	1		*FRONT HEADLAMP LH	Cracked	2,518.00 FL	*2,450.00 FL
15	1		*FRONT LEFT HEADLAMP BRACKET	Not Necessary	76.00 FL	*- FL
16	1		*FRONT LEFT FENDER (NPA)	Repair	0.00 FL	*- FL
17	1		*FRONT BONNET (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*FRONT BUMPER DIFFUSER ACCESSORIES CARBON M3 SERIES (CRACKED)	Not Consistent With The Impact	2,680.00 FS	*- FS
19	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	68.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,717.00	4,670.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	448.45	233.50
Total Parts (\$\$)	11,268.55	4,436.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR & RENEW FRONT AFFECTED ACCIDENT AREAS	New	1,200.00	400.00
2	TO PUTTY SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,600.00	400.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO CONDUCT AC LEAKAGE TEST	New	200.00	0.00
5	TO CONDUCT RADIATOR LEAKAGE TEST	New	200.00	0.00
6	TO RE-POSITION ,DRILL & INSTALL FRONT ANGLE SENSOR }	New	150.00	50.00
7	TO CONDUCT & RESET BMW DIAGNOSTIC MANAGEMENT }	New	500.00	0.00
8	TO RUST PROOF AFFECTED AREAS	New	200.00	0.00
Gross Labour Cost (S\$)			4,100.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >