

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/A1420007513/UKS3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 555907

at Workshop m/s 200m

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 98k.

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

8130
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 555907 Yr Regn: 11/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: BMW M3 C.C. 3999

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 116033 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBSWL92020P371129

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/50ZR19

R: 305/30ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 16/7/20

D.O.I. 22/7/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 10/11

COR 13-11-2028 LTA26693

25/8/20 4/5 @ 4200 confirmed with Elin

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Report Format : _____

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Lump Sum / I.B.I.: (\$)

TOTAL



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Mr. Chandra

Car Number: SJJ90T

Model : BMW M3 4.0 MT

Damaged Area: (Front Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

not Authorized
han
2/5 4200
22/7/20
3 days.

Parts / Material :

1	Front Bumper (M3)	re/turn 1650	\$	2,480.00	✓
2	Front Bumper Centre Air-Grille	^^	\$	586.00	X
3	Front Bumper LH Grille	^^	\$	365.00	X
4	Front Bumper LH Headlamp Nozzle Garnish	M.S 45	\$	150.00	✓
5	Front Bumper LH Headlamp Nozzle	CNA	\$	297.00	✓
6	Front Bumper Sensor @ 475.00	^^	\$	950.00	X
7	Front Bumper Sensor Holder @ 28.00	^^	\$	112.00	X
8	Front Bumper Sensor Holder Ring @ \$9.00	^^	\$	36.00	X
9	Front Bumper sponge	CNA	\$	168.00	✓
10	Front Bumper Left Corner Mount	^^	\$	148.00	X
11	Front Bumper Top Carrier	^^	\$	397.00	X
12	Front Bumper Reinforcement	^^	\$	586.00	X
13	Front Bumper Clips	re 60	\$	100.00	✓
14	Front Headlamp LH	CNA 2400	\$	2,518.00	✓
15	Front Left Headlamp Bracket	^^	\$	76.00	X
16	Front Left Fender	^^		Repair	X
17	Front Bonnet	^^		Repair	X
Parts :			\$	8,969.00	
Less Parts 5% :			\$	448.45	
Total Parts :			\$	8,520.55	

Special Net Items :

Front Bumper Diffuser Accessories Carbon M3 Series	CNA n/c	\$	2,680.00	X
Rear Number Plate W/Garnish	^^	\$	68.00	X
Total S/N Parts :		\$	2,748.00	

Labour :

To Remove, Repair & Renew Front Affected Accident Areas	\$	1,200.00	400
To Putty, Spray Paint on Affected Accident Areas	\$	1,600.00	400
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Conduct AC Leakage Test	\$	200.00	X
To Conduct Radiator Leakage Test	\$	200.00	X
To Re-Position, Drill & Install Front Angle Sensor	\$	150.00	
To Conduct & Rest BMW Diagnostic Management	\$	500.00	350
To Rust Proof Affected Areas	\$	200.00	X
Total Labour :		\$	4,100.00

TOTAL PARTS :	\$	8,520.55
TOTAL SPECIAL NET ITEM :	\$	2,748.00
TOTAL LABOUR :	\$	4,100.00
TOTAL REPAIR COST :	\$	15,368.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 4670
52
P. 4436.50
L- 870.00
5306.50
202
4245