



Your Ref : SNM20D202334/C02/TKL

Date: 18th August 2020

Our Ref : CS/CTI20007515/Avf3s2

M/s China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKW 899Y
ACCIDENT ON 19/06/2020 INSURED VEHICLE SKE 764Y**

Instruction was received to inspect the vehicle Reg. No. SKW 899Y. The inspection was conducted on 21/07/2020 at the premises of M/s SK Automobile Pte Ltd, 8 Kaki Bukit Ave 4 #08-45 Premier @ Kaki Bukit Singapore 415875.

The following vehicle information was recorded:


Registration Number	: SKW 899Y
Make/Model	: VOLVO S60
Year of Registration	: 2015
Body Colour	: Beige
Chassis Number	: YV1FS40LDG2399797
Engine Capacity	: 1969 cc

The vehicle sustained damages at the front portion, o/s and n/s body and undercarriage.
(Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 69,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 51,927.00)
Nett Liability	<u>S\$ 17,073.00</u> =====

Vehicle Inspected By:



ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.