

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007522/KES3Q2

Date: 11/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900172370

Claimant
Vehicle No : GX7024B **Insured Vehicle No :** SMP133L

Date of Loss: 17/07/2020 Nature of Claim: TP Claim No: 8548412905SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX7024B	Engine No:	QD32193064
Make & Model:	NISSAN CABSTAR, 3.1 (M)	Chassis No:	JN1SF4F23Z0852733
Reg. Date:	19/08/2004 (Man. Year: 2004)	Odometer:	485564 km
Colour:	Silver		
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155R12X8(D)
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Dunlop 9/9 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Dunlop 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,514.24	8,286.81	7,227.43	46.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,840.00	460.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,814.24	10,126.81	7,687.43	43.15
Approved Total (Overridden) (\$\$)		8,000.00		
(\$\$)	17,814.24	8,000.00	9,814.24	55.09
+ GST 7.00/7.00% (\$\$)	1,247.00	560.00	687.00	55.09
Nett Amount (\$\$)	19,061.24	8,560.00	10,501.24	55.09
+ Loss of Use (10.0 x S\$100.00/day) (\$\$)		1,000.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		9,567.45		

INSPECTION

Date of Assignment: 21/07/2020

Date Inspected: 22/07/2020 Inspected At:

Kum Chew Motor Workshop (HQ)
12 Sin Ming Industrial Estate, #01-71
Singapore 575656

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR -R/H	Bent	1,694.50 FN	*1,694.50 FN
2	1		*FRT DOOR SIDE PILLAR -R/H	Bent	1,460.10 FN	*1,460.10 FN
3	1		*FRT DOOR SIDE SEAL -RH	Serviceable	51.10 FN	*- FN
4	1		*FRT DOOR HINGE (TOP)-R/H	Repair	149.30 FN	*- FN
5	1		*FRT DOOR HINGE (LOWER)-R/H	Distorted	149.30 FN	*149.30 FN
6	1		*FRT DOOR CHECKER -R/H	Serviceable	76.50 FN	*- FN
7	1		*FRT STEP PANEL -R/H	Repair	720.70 FN	*- FN
8	1		*STEP PANEL GARNISH -R/H	Dented / Cut	78.50 FN	*78.50 FN
9	1		*FRT SIDE PANEL GARNISH -RH	Serviceable	78.10 FN	*- FN
10	1		*FRT SIDE PANEL -RH	Buckled	551.60 FN	*551.60 FN
11	1		*CENTRAL PANEL TOP GARNISH	Serviceable	664.50 FN	*- FN
12	1		*FRT BUMPER	Bent	820.80 FN	*820.80 FN
13	1		*FRT BUMPER REINFORCEMENT	Bent	822.30 FN	*822.30 FN
14	1		*FRT BUMPER BRACKET	Repair	91.30 FN	*- FN
15	1		*FRT GRILLE	Serviceable	391.50 FN	*- FN
16	1		*FRT NISSAN EMBLEM	Not Necessary	79.70 FN	*- FN
17	1		*FRT CABSTAR EMBLEM	Serviceable	35.20 FN	*- FN
18	1		*FRT HEADLAMP -RH	Mtg Cracked	381.40 FN	*381.40 FN
19	1		*FRT SIDE LAMP -RH	Broken	216.90 FN	*216.90 FN
20	1		*FRT LOWER ARM -R/H	Distorted	320.60 FN	*320.60 FN
21	2		*REAR AXLE HUP CAP	Serviceable	958.80 FN	*- FN
22	2		*REAR AXLE BEARING HUP	Necessary	334.60 FN	*334.60 FN
23	1		*REAR WHEEL GARNISH (METAL) -L/H	Bent	140.30 FN	*140.30 FN
24	1		*FRT DOOR (CABSTAR) STICKER	Necessary	76.80 FS	*76.80 FS
25	1		*FRT KNUCKLE -R/H	Bent	218.90 FS	*218.90 FS
26	1		*FRT KNUCKLE BEARING -RH	Necessary	119.80 FS	*119.80 FS
27	1		*FRT SUSPENSION -RH	Distorted	132.00 FS	*132.00 FS
28	1		*FRT RIM -RH (LOCAL PURCHASE)	Bent	287.50 FS	*50.00 FS
29	1		*REAR AXLE (LOCAL PURCHASE)	Bent	4,916.30 FS	*1,100.00 FS
30	1		*REAR RIM -L/H	Dented	207.10 FS	*50.00 FS
31	1		*FRT TYRE -RH (80%)	Cut	180.00 FS	*144.00 FS
32	1		*REAR TYRE -LH (80%)	Cut	135.00 FS	*121.50 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	16,541.00	8,983.90
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,026.76	697.09

Total Parts (\$\$)	15,514.24	8,286.81
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO COMPUTER 4 WHEEL ALIGNMENT	New	150.00	100.00
2	TO PULL ,KNOCK ON ACCIDENT PORTION & CHARGE ABOVE PART	New	680.00	600.00
3	TO SPRAY & PAINT ON FRT & REAR ACCIDENT PORTION	New	850.00	700.00
4	TO ANTI-RUST AFFECTED AREAS	New	60.00	60.00
5	TO CHECK WIRING FUNCTION	New	60.00	20.00
6	TO DISMANTLE ,REPLACE ,REFIX FRT & REAR UNDERCARRIAGE	New	350.00	300.00
7	TO DISMANTLE ,REFIX FRT DOOR GLASS ,GLASS GEAR ,MOTOR ,RUBBER & DOOR MECHANISM	New	150.00	60.00
Gross Labour Cost (\$\$)			2,300.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >