



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2005520
INV Date 12/08/2020
Reference CS/AGI20007524/Asf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SFL 7313S
Insured Veh. SGL 8455Y
Claim No. C10006780
Policy No.
Accident Date 21/07/2020
Inspection Date 21/07/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20007524/Asf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 12-08-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGL 8455Y	Veh. Inspected	SFL 7313S
Policy No.		Coverage (\$)	0.00
Claim No.	C10006780	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	21/07/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMFD16308S216535	Colour	BLACK
Odometer	258866	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	6 mm
L/H Front Tyre	205/55 R16	DUNLOP	6 mm
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/07/2020	Inspection Date	21/07/2020
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
--	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFL 7313S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	638.00	638.00
1	FRONT BUMPER NUMBER PLATE GARNISH	DEFORMED	34.10	34.10
1	FRONT BUMPER REINFORCEMENT	BENT	218.00	218.00
1	FRONT BUMPER RH FOGLAMP	CRACKED	250.40	250.40
1	FRONT BUMPER RH FOGLAMP BRACKET	NOT NECESSARY	16.50	-
1	FRONT BUMPER RH FOGLAMP GARNISH	CRACKED	22.20	22.20
2	FRONT BUMPER SIDE RETAINER L/R @\$12.80	NECESSARY	25.60	25.60
1	FRONT GRILLE	CRACKED	84.60	84.60
1	FRONT GRILLE "LOGO" EMBLEM	NECESSARY	23.40	23.40
1	FRONT GRILLE OUTER COVER	CUT	175.30	175.30
1	FRONT GRILLE TOP GARNISH	DEFORMED	65.70	65.70
2	FRONT HEADLAMP L/R @\$912.10	CRACKED	1,824.20	1,824.20
2	FRONT HEADLAMP LOWER BRACKET L/R @\$29.10	BENT	58.20	58.20
1	REAR BOOTLID	DENTED	610.70	610.70
1	REAR BOOTLID "1.8" EMBLEM	NECESSARY	17.00	17.00
1	REAR BOOTLID "CIVIC" EMBLEM	NECESSARY	29.10	29.10
1	REAR BOOTLID "I-VTEC" EMBLEM	NECESSARY	34.10	34.10
1	REAR BOOTLID "LOGO" EMBLEM	NECESSARY	25.70	25.70
2	REAR BOOTLID HINGES L/R @\$48.60	NOT NECESSARY	97.20	-
2	REAR BOOTLID INNER LOWER RUBBER STOPPER L/R @\$12.50	NOT NECESSARY	25.00	-
2	REAR BOOTLID INNER RUBBER STOPPER L/R @\$18.50	NOT NECESSARY	37.00	-
1	REAR BOOTLID INNER TRIM BOARD	DEFORMED	133.70	133.70
1	REAR BOOTLID LOCK CABLE	NOT NECESSARY	87.60	-
1	REAR BOOTLID LOCK STRIKER	NOT NECESSARY	27.50	-
1	REAR BOOTLID MECHANISM LOCK	DAMAGED	194.50	194.50
1	REAR BOOTLID NUMBER PLATE LAMP GARNISH	CRACKED	121.60	121.60
2	REAR BOOTLID NUMBER PLATE LAMP L/R @\$15.50	NOT NECESSARY	31.00	-
2	REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R @\$15.20	NECESSARY	30.40	30.40
2	REAR BOOTLID REFLECTOR L/R @\$145.10	CRACKED	290.20	290.20

Report Ref No. CS/AGI20007524/Asf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOTLID WEATHERSTRIP	CUT	97.60	97.60
1	REAR BUMPER	DISTORTED	638.00	638.00
1	REAR BUMPER EXHAUST COVER	DAMAGED	19.50	19.50
2	REAR BUMPER MUDFLAT L/R @\$74.90	NOT NECESSARY	149.80	-
2	REAR BUMPER SIDE RETAINER L/R @\$14.90	NECESSARY	29.80	29.80
1	REAR END PANEL	DISTORTED	300.50	300.50
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	56.10	56.10
2	REAR EXHAUST CHROME TAIL PIPE L/R @\$93.40	CUT	186.80	186.80
1	REAR EXHAUST GASKET	NOT NECESSARY	38.50	-
1	REAR EXHAUST HEAT COVER	NOT NECESSARY	43.80	-
2	REAR EXHAUST RUBBER MOUNTING @\$16.00	NOT NECESSARY	32.00	-
1	REAR EXHAUST SILENCER BOX	BENT	535.00	535.00
2	REAR FENDER INNER TRIM BOARD L/R @\$145.90	DEFORMED	291.80	291.80
1	REAR FLOOR LOWER JET PANEL	DENTED	265.00	265.00
1	REAR FLOOR PANEL	BUCKLED	992.20	992.20
1	REAR FLOOR PANEL TOP BOARD COVER	DEFORMED	316.00	316.00
2	REAR FLOOR SIDE PANEL L/R @\$205.00	TO REPAIR SEE LABOUR	410.00	-
1	REAR FLOOR SPONGE COMPARTMENT TRAY	CRACKED	56.50	56.50
2	REAR TAILLAMP INNER BLACK GASKET L/R @\$10.50	NECESSARY	21.00	21.00
2	REAR TAILLAMP INNER PANEL L/R @\$65.70	TO REPAIR SEE LABOUR	131.40	-
2	REAR TAILLAMP L/R @\$226.20	CRACKED	452.40	452.40
2	REAR TAILLAMP LOWER BRACKET L/R @\$14.90	BENT	29.80	29.80
1	REAR SPARE TYRE SCREW LOCK	DAMAGED	45.00	45.00
1	REAR RH FENDER INNER AIR VENT	NOT NECESSARY	38.00	-
1	FRONT RADIATOR	NOT NECESSARY	1,507.40	-
	LESS 20% DISCOUNT		-2,382.48	-1,847.94
			9,529.92	7,391.76
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER NUMBER PLATE (SN)	DENTED	25.00	25.00

Report Ref No. CS/AGI20007524/Asf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	20.00
1	SET REAR BOOTLID INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR BOOTLID NUMBER PLATE (SN)	BENT	25.00	25.00
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	50.00	10.00
2	SET REAR FENDER INNER TRIM BOARD CLIPS L/R @\$50.00 (SN)	NECESSARY	100.00	60.00
1	REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	300.00	200.00
2	SET REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	20.00
1	TRIANGLE WARNING SIGN (SN)	CRACKED	350.00	150.00
			1,670.00	860.00
	<u>LABOUR</u>			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR).		100.00	30.00
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	70.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		140.00	120.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		800.00	400.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER.		1,400.00	1,200.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		100.00	80.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR FLOOR SIDE PANEL L/R AND REAR TAILLAMP INNER PANEL L/R.		2,600.00	1,600.00

Report Ref No. CS/AGI20007524/Asf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	80.00
	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR.		80.00	60.00
			5,440.00	3,640.00
GRAND TOTAL			16,639.92	11,891.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00

Report Ref No. CS/AGI20007524/Asf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.