

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20007536/T1PS3Q2
Date: 12/07/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMM4850P	Insured Vehicle No :	SHA6992Y
Date of Loss:	18/07/2020	Nature of Claim:	TP
		Claim No:	MCT20070251

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM4850P		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B3883234
Reg. Date:	28/06/2019 (Man. Year: 2019)	Chassis No:	GK33413711
Colour:	Red	Odometer:	74555 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	424.40	0.00	424.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	430.00	700.00	61.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,554.40	430.00	1,124.40	72.34
+ GST 7.00/7.00% (S\$)	108.81	30.10	78.71	72.34

Nett Amount (S\$)	1,663.21	460.10	1,203.11	72.34
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		587.55		

INSPECTION

Date of Assignment: 21/07/2020

Date Inspected: 05/10/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
 Blk 3 Pioneer Road North, #01-18
 Singapore 628457

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Feb 2021)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM4850P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	492.60 FL	*- FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	16.90 FL	*- FL
3	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$\$)	530.500.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	106.100.00
					Total Parts (\$\$)	424.400.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK RR BUMPER LOWER LID ,WELD ,REMOVE & REPLACE ABOVE PART	New	500.00	200.00
2	TO SPRAY PAINTING ON REAR BUMPER LOWER LID & AFFECTED AREA	New	600.00	200.00
3	TO CHECK WIRING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,130.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >