

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007542/KEA3Q2
Date: 30/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800113451-01
Claimant Vehicle No :	SMC8645S	Insured Vehicle No :	SLG9299S
Date of Loss:	17/07/2020	Nature of Claim:	TP
		Claim No:	6582446476SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC8645S		
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Engine No:	D4FDJD025998
Reg. Date:	26/07/2018 (Man. Year: 2018)	Chassis No:	KNAHU815VJ7211721
Colour:	Red	Odometer:	144401 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,516.20	3,846.60	669.60	14.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	1,160.00	510.00	30.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,186.20	5,006.60	1,179.60	19.07
+ GST 7.00/7.00% (S\$)	433.03	350.46	82.57	19.07

Nett Amount (\$\$)	6,619.23	5,357.06	1,262.17	19.07
+ Loss of Use (5.0 x S\$160.00/day) (\$\$)		800.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		6,159.06		
Global Sum Settlement (\$\$)		6,150.00		

INSPECTION

Date of Assignment: 20/07/2020

Date Inspected: 21/07/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Chew Goon Motor (AMK)
 Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	695.00 FL	*695.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
3	1		*FRONT BUMPER CORNER RETAINER LH	Distorted	18.00 FL	*18.00 FL
4	1		*FRONT BUMPER FOG LAMP LH	Serviceable	206.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER	Cut	155.00 FL	*155.00 FL
6	1		*HEADLAMP LH	Cut	1,558.00 FL	*1,558.00 FL
7	1		*FRONT WHEEL RIM	Dented	605.00 FL	*605.00 FL
8	1		*FRONT SHOCK ABSORBER	Serviceable	334.00 FL	*- FL
9	1		*FRONT KNUCKLE ARM	Bent	344.00 FL	*344.00 FL
10	1		*FRONT KNUCKLE ARM BEARING	Necessary	237.00 FL	*237.00 FL
11	1		*FRONT KNUCKLE ARM BEARING HUB	Bent	198.00 FL	*198.00 FL
12	1		*FRONT LOWER ARM	Distorted	429.00 FL	*429.00 FL
13	1		*AIR CLEANER RESONATOR	Serviceable	204.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,018.00	4,274.00
- List Item Discount on L Items 10.00/10.00% (\$)	501.80	427.40
Total Parts (\$)	4,516.20	3,846.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	20.00
2	TO DISMANTLE /REPLACE FRONT UNDER CARRIAGE TO FACILITATE REPAIR	New	200.00	160.00
3	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
4	TO CONDUCT HIGH SPEED BALANCING	New	80.00	20.00
5	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF HEADLAMP PANEL ,FRONT N/S FENDER ,FRONT DOOR AND PARTS REPLACEMENT	New	580.00	300.00
6	TO RESPRAY AFFECTED AREAS	New	700.00	600.00
Gross Labour Cost (S\$)			1,670.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >