

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: Z21880/000 GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 20.07.2020

Accident Date : 17.07.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount \$ cts.
	Estimate Cost Of Repair To "Kia Carens 1.7" Reg. No. SMC8649S Claiming Against Your Insured Reg. No. SLG9299S		
1pc	Front Bumper		695.00
10pcs	Front Bumper Clips	3.5	35.00
1pc	Front Bumper Corner Retainer LH		18.00
1pc	Front Bumper Fog Lamp LH		206.00
1pc	Front Bumper Fog Lamp Cover		155.00
1pc	Headlamp LH		1,558.00
1pc	Front Wheel Rim		605.00
1pc	Front Shock Absorber		334.00
1pc	Front Knuckle Arm		344.00
1pc	Front Knuckle Arm Bearing		237.00
1pc	Front Knuckle Arm Bearing Hub		198.00
1pc	Front Lower Arm		429.00
1pc	Air Cleaner Resonator		204.00
	Less 10%		5,018.00
			501.80
			4,516.20
	To Conduct Electrical Check, Focus Headlamp		30.00
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		200.00
	To Conduct Computerize Wheel Alignment Test		80.00
	To Conduct High Speed Balancing		80.00
	Labour Charge - Panel Beating, Repairing Of Headlamp Panel, Front N/S Fender, Front Door and Parts Replacement		580.00
	To Respray Affected Areas		700.00
		Total :	6,186.20

LKIC Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: