



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2100259

INV Date 13/01/2021

Reference CC4/EQI20007543/Upa3q2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SLD 299S

Insured Veh. SLM 815E

Claim No. DM20HO01020/SG

Policy No. DMCFHQ19-000086

Accident Date 28/03/2020

Inspection Date 24/07/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CC4/EQI20007543/Upa3q2 Date: 13/01/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLM 815E	Veh. Inspected	SLD 299S	
Policy No.	DMCFHQ19-000086	Coverage (\$)	0.00	
Claim No.	DM20HO01020/SG	Excess (\$)	0.00	
Assign From	JANICE GOH	Assign Date	20/07/2020	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 HATCHBACK (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM44A8G0342844	Colour	GREY	
Odometer	41768 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOYO	6 mm	
L/H Front Tyre	205/60 R16	TOYO	6 mm	
R/H Rear Tyre	205/60 R16	TOYO	6 mm	
L/H Rear Tyre	205/60 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/03/2020	Inspection Date	24/07/2020	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 299S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED / DEFORMED	1,118.40	1,118.40
2	RIVET ,REAR BUMPER	NECESSARY	16.00	16.00
4	GROMMET ,REAR BUMPER	NECESSARY	10.80	10.80
6	RIVET, REAR BUMPER	NECESSARY	34.20	34.20
4	RIVET ,REAR BUMPER	NECESSARY	22.80	22.80
2	TAPE PROTECTOR ,REAR BUMPER	NOT NECESSARY	17.20	-
1	BRACKET CENTER	NOT NECESSARY	5.40	-
1	GASKET LHS, TAILLAMP	NECESSARY	22.00	22.00
1	GASKET RHS, TAILLAMP	NECESSARY	22.00	22.00
1	REAR REINFORCEMENT	TO REPAIR SEE LABOUR	564.20	-
1	ANTENNA	NOT NECESSARY	111.10	-
			1,944.10	1,246.20
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
	<u>LABOUR</u>			
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT ,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT .INCLUSIVE OF THE REPAIR OF REAR REINFORCEMENT .		1,320.00	660.00
	TO RESPRAY REAR BUMPER AND REPAIR REINFORCEMENT .		1,260.00	630.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO TRANSFRT REVERSE SENSORS.		330.00	180.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
			3,760.00	1,740.00
	GRAND TOTAL		5,804.10	3,006.20

Report Ref No. CC4/EQI20007543/Upa3q2



RECOMMENDED COST OF REPAIRS			3,006.20
-----------------------------	--	--	-----------------

Report Ref No. CC4/EQI20007543/Upa3q2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLD 299S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLD 299S

RE-INSPECTION

