

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20007549/R1VF3E2

Date: 30/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2070101113
<b>Claimant Vehicle No :</b> XE5168G	<b>Insured Vehicle No :</b> GBJ3473Y
Date of Loss: 08/07/2020	Nature of Claim: TP Claim No: 6757825258SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>XE5168G</b>		
Make & Model:	MITSUBISHI FUSO, 10.7 D FV70HJA00064 (M)	Engine No:	470912C0470196
Reg. Date:	10/09/2019 (Man. Year: 2019)	Chassis No:	FP70HDA00023
Colour:	Blue	Odometer:	0 km
Engine Capacity:	10677 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	21/07/2020	
Date Inspected:	27/07/2020 Inspected At:	15 Pioneer Walk Pioneer Repairer : Lys Engineering - Pioneer (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	0.00 F	*- F
2	1		*FRT CORNER PANEL LH	Cracked	0.00 F	*- F
3	1		*FRT LH HEADLAMP ASSY COVER	Scratched	0.00 F	*- F
4	1		*FRT LH DOOR	Bent	0.00 F	*- F
5	1		*FRT LH DOOR SIGNAL LIGHT	Missing	0.00 F	*- F
6	1		*FRT LH DOOR GLASS RUBBER	Necessary	0.00 F	*- F
7	1		*FRT LH DOOR GLASS SEALANT	Necessary	0.00 F	*- F
8	1		*FRT LH DOOR RUBBER	Necessary	0.00 F	*- F
9	1		*FRT LH DOOR OUTER GLASS	Scratched	0.00 F	*- F
10	1		*FRT STEP PANEL LH	Cracked	0.00 F	*- F
11	1		*FRT STEP PANEL INNER GARNISH LH	Cracked	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (\$\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**