




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20007562/EUsf3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 04-08-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 1145J	Veh. Inspected	SDV 133L
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2002164/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/07/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER	c.c	1986
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	ZSU600078626	Colour	RED
	Odometer	76485	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	MICHELIN	5 mm
	L/H Front Tyre	235/55 R18	MICHELIN	5 mm
	R/H Rear Tyre	235/55 R18	MICHELIN	5 mm
	L/H Rear Tyre	235/55 R18	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/07/2020	Inspection Date	23/07/2020
	Survey held at	RYDER AUTO WORKSHOP LLP 2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	