



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 25P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LAMP, BLINKER:FRONT, RIGHT, FOR MB OC500 LE	CRUMPLED	155.30	155.30
1	HEADLAMP FOR MERCEDES OC500 LE, RIGHT	SERVICEABLE	1,276.50	-
1	LAMP, FRONT FOG, RIGHT SIDE FOR MB OC500LE	SERVICEABLE	300.00	-
1	COVER, HEADLAMP:RH, FIBREGLASS, MB OC500	TO REPAIR SEE LABOUR	621.00	-
	LESS 10% DISCOUNT		-	-15.53
			2,352.80	139.77
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF COVER, HEADLAMP:RH, FIBREGLASS, MB OC500.		1,060.00	530.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		446.00	354.00
			1,506.00	884.00
GRAND TOTAL			3,858.80	1,023.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				800.00

Report Ref No. NS/INC20007563/Qsf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.