

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20007567/T1ES3Q2**Date:** 02/02/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100424860  
**Claimant**  
**Vehicle No :** SKZ1323U **Insured Vehicle No :** SKU7453P  
Date of Loss: 21/07/2020 Nature of Claim: TP Claim No: 9229373337SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ1323U**  
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4026134  
Reg. Date: 11/01/2016 (Man. Year: 2015) Chassis No: RU11106121  
Colour: White Odometer: 69577 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,698.00	2,184.00	5,514.00	71.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,190.00	1,470.00	1,720.00	53.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,888.00</b>	<b>3,654.00</b>	<b>7,234.00</b>	<b>66.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		
<b>(S\$)</b>	10,888.00	2,900.00	7,988.00	73.37
<b>+ GST 7.00/7.00% (S\$)</b>	762.16	203.00	559.16	73.37
<b>Nett Amount (S\$)</b>	<b>11,650.16</b>	<b>3,103.00</b>	<b>8,547.16</b>	<b>73.37</b>
<b>+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		535.00		
<b>Nett Liability (S\$)</b>		<b>3,638.00</b>		

INSPECTION

Date of Assignment: 22/07/2020  
Date Inspected: 27/07/2020 Inspected At: MBM Wheelpower Pte Ltd (HQ)  
160 Sin Ming Drive #06-02, Sin Ming  
AutoCity  
Singapore 575722  
Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,700.00 FL	*1,100.00 FL
2	1		*TAIL GATE GLASS MOULDING	Necessary	120.00 FL	*120.00 FL
3	1		*WEATHERSTRIP, TAILGATE	Not Necessary	150.00 FL	*- FL
4	2		*TAIL GATE HINGE	Not Necessary	60.00 FL	*- FL
5	1		*TAILGATE SPOILER	Not Necessary	250.00 FL	*- FL
6	1		*TAIL GATE INNER TRIM	Not Necessary	480.00 FL	*- FL
7	1		*TAIL GATE UPPER LINING	Not Necessary	120.00 FL	*- FL
8	1		*TAIL GATE SIDE INNER LINING LH	Not Necessary	50.00 FL	*- FL
9	1		*TAIL GATE SIDE INNER LINING RH	Not Necessary	50.00 FL	*- FL
10	1		*TAIL GATE EMBLEM VEZEL	Necessary	50.00 FL	*50.00 FL
11	1		*TAIL GATE EMBLEM HONDA LOGO	Necessary	20.00 FL	*20.00 FL
12	1		*TAIL GATE LAMP LH	Not Necessary	300.00 FL	*- FL
13	1		*TAIL GATE LAMP RH	Not Necessary	300.00 FL	*- FL
14	1		*REAR BUMPER	Deformed	1,000.00 FL	*850.00 FL
15	1		*REAR BUMPER REFLECTOR LH	Cut	150.00 FL	*150.00 FL
16	1		*REAR BUMPER REFLECTOR RH	Not Necessary	150.00 FL	*- FL
17	1		*REAR BUMPER CORNER PANEL RH	Not Necessary	380.00 FL	*- FL
18	1		*REAR BUMPER CORNER PANEL LH	Repair	380.00 FL	*- FL
19	1		*REAR BUMPER CORNER PANEL INNER LINING RH	Not Necessary	250.00 FL	*- FL
20	1		*REAR BUMPER CORNER PANEL INNER LINING LH	Not Necessary	250.00 FL	*- FL
21	1		*REAR BUMPER CORNER COVER BRACKET RH	Not Necessary	75.00 FL	*- FL
22	1		*REAR BUMPER CORNER COVER BRACKET LH	Not Necessary	75.00 FL	*- FL
23	1		*REAR BUMPER CROSS MEMBER	Not Necessary	200.00 FL	*- FL
24	10		*REAR BUMPER CLIP	Necessary	90.00 FL	*90.00 FL
25	1		*REAR BUMPER UNDERCOVER	Not Necessary	200.00 FL	*- FL
26	1		*FENDER INNER LINER RH	Not Necessary	100.00 FL	*- FL
27	1		*FENDER INNER LINER LH	Not Necessary	100.00 FL	*- FL
28	1		*WHEEL ARCH PROTECTOR RH	Not Necessary	150.00 FL	*- FL
29	1		*WHEEL ARCH PROTECTOR LH	Not Necessary	150.00 FL	*- FL
30	1		*TAIL LAMP RH	Not Necessary	500.00 FL	*- FL
31	1		*TAIL LAMP LH	Not Necessary	500.00 FL	*- FL
32	1		*REAR END PANEL	Repair	650.00 FL	*- FL
33	1		*REAR END PANEL TOP GARNISH	Not Necessary	85.00 FL	*- FL
34	1		*REAR NUMBER PLATE & HOLDER	Not Necessary	50.00 FS	*- FS
35	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS
36	1		*TAIL GATE SEALANT	Necessary	80.00 FS	*80.00 FS
37	1		*REAR BUMPER SENSOR	Not Working	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,515.00</b>	<b>2,660.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,817.00	476.00
<b>Total Parts (\$\$)</b>	<b>7,698.00</b>	<b>2,184.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	New	1,600.00	600.00
2	TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPAIR.	New	150.00	60.00
3	TO REMOVE & INSTALL TAILGATE GLASS.	New	180.00	120.00
4	TO APPLY ANTI RUST COATING.	New	80.00	30.00
5	TO CHECK & RECONNECT ALL NECESSARY WIRING.	New	100.00	30.00
6	TO REMOVE & INSTALL REVERSE SENSOR.	New	80.00	30.00
7	TO SPRAY PAINT ON THE AFFECTED AREAS.	New	1,000.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,190.00</b>	<b>1,470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >