

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
 #02-19 SINGAPORE 417883
 TEL: 6 5090052 FAX: 6 7479402

22-07-20

OUR REF NO. SJG 5817Y

CHAN FEI LOONG, DESMOND
 BLK 67, BEDOK SOUTH
 AVE 3, #21-500
 SINGAPORE 460067

K1ZT2603023095

ESTIMATE BILL FOR VEHICLE NO. SJG 5817Y
MODEL : TOYOTA ALLION

LIST ITEM

1) BOOT LID	Dented		\$ 1,083.00	✓	860.20
2) BOOT LID WEATHERSTRIPE	cut		\$ 231.00	✓	
3) BOOT LID HINGE	x2 m	2 PCS @ \$ 211.00	\$ 422.00	+	
4) BOOT LID BADGE	x2		\$ 61.70	✓	
5) BOOT LID EMBLEM ' ALLION '	} Jan		\$ 58.40	✓	
6) BOOT LID EMBLEM ' A15 '			\$ 53.15	✓	
7) BOOT LID LOCK	Damaged		\$ 343.00	-	
8) BOOT LID STRIKER	x2 m		\$ 34.00	X	
9) BOOT LID INNER LINNING	x2 m		\$ 182.00	X	
10) BOOT LID INNER LINNING CLIP	x2 m	13 PCS @ \$ 12.90	\$ 167.70	+	
11) BOOT LID STOPPER	x2 m	4 PCS @ \$ 43.90	\$ 175.60	+	
12) BOOT LID HINGE GARNISH	} Jan	2 PCS @ \$ 158.00	\$ 316.00	X	
13) BOOT LID HINGE GARNISH CLIP		4 PCS @ \$ 12.90	\$ 51.60	X	
14) BOOT LID OUTER CHROME	cut		\$ 326.00	✓	
15) BOOT LID OUTER CHROME CLIP	m	3 PCS @ \$ 18.90	\$ 56.70	10	
16) REAR LICENCE PLATE LAMP	x2 m	2 PCS @ \$ 83.00	\$ 166.00	X	
17) TAIL LAMP	LH cut, RH reserved	2 PCS @ \$ 398.00	\$ 796.00	398	
18) TAIL LAMP BASE PANEL	Rep	2 PCS @ \$ 315.20	\$ 630.40	X	
19) TAIL LAMP CLIP	NEC	2 PCS @ \$ 10.50	\$ 21.00	✓	
20) REAR BUMPER	Distorted		\$ 1,571.20		855

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
 #02-19 SINGAPORE 417883
 TEL: 6 5090052 FAX: 6 7479402

21) REAR BUMPER CLIP	<i>new</i>	8 PCS @ \$ 8.90	\$ 71.20	<i>30</i>
22) REAR BUMPER SIDE ATTACHMENT	<i>new</i>	2 PCS @ \$ 121.00	\$ 242.00	<i>136</i>
23) REAR BUMPER BRACKET (LH)	<i>Dented</i>		\$ 55.86	<i>✓</i>
24) REAR BUMPER SPLASH SHIELD (LH)			\$ 121.00	<i>+</i>
25) REAR BUMPER SPLASH SHIELD CLIP (LH)	<i>2 pair new</i>	6 PCS @ \$ 12.90	\$ 77.40	<i>+</i>
26) REAR BUMPER REFLECTOR (LH)	<i>cracked</i>		\$ 280.00	<i>8390</i>
27) REAR END PANEL	<i>Dented</i>		\$ 680.00	<i>584.20</i>
28) REAR PANEL INNER GARNISH	<i>Dented</i>		\$ 181.70	<i>✓</i>
29) REAR PANEL INNER GARNISH CLIP	<i>new</i>	2 PCS @ \$ 12.90	\$ 25.80	<i>10</i>
30) REAR ANTENNA SENSOR	<i>cracked</i>		\$ 138.00	<i>✓</i>
31) SPARE TYRE PANEL	<i>Repis</i>		\$ 804.20	<i>+</i>
32) SPARE TYRE BOARD	<i>Dented</i>		\$ 273.00	<i>✓</i>
33) REAR FENDER (LH)	<i>Repis</i>		\$ 1,052.10	<i>+</i>
34) REAR FENDER INNER BOARD (LH)	<i>new</i>		\$ 561.20	<i>+</i>
35) REAR FENDER INNER BOARD CLIP (LH)		10 PCS @ \$ 12.90	\$ 129.00	<i>+</i>
36) REAR FENDER AIR VENT (LH)	<i>new</i>		\$ 118.00	<i>+</i>
37) REAR WINDSCREEN MOULDING	<i>new</i>		\$ 220.00	<i>+</i>
			\$ 11,777.21	
			\$ 2,944.30	
			\$ 8,832.91	

LESS DISCOUNT - 25%

SPECIAL NETT ITEM

1) REAR LICENCE PLATE	<i>Beit</i>		\$ 55.00	<i>✓</i>
2) REVERSE SENSOR WITH CONTROL UNIT	<i>new</i>		\$ 320.00	<i>200</i>
3) REAR WINDSCREEN INNERSEAL	<i>new</i>		\$ 60.00	<i>+</i>
4) REAR WINDSCREEN GUM	<i>new</i>		\$ 60.00	<i>+</i>
			\$ 495.00	

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	\$	50.00	30
2) TO APPLY UNDER SEALING ON AFFECTED AREAS	\$	120.00	60
3) TO REMOVE AND REFIX REAR WINDSCREEN	\$	320.00	x
4) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	\$	120.00	50
5) TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINNING, TRIM, GARNISH, UPHOLSTERY AND ETC	\$	220.00	60
6) TO REMOVE AND REFIX PETROL TANK, PIPING SYSTEM, BRACKET AND ETC	\$	280.00	x
7) TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT	\$	220.00	80
8) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC	\$	2,200.00	800
9) TO RESPRAY ON THE AFFECTED AREAS	\$	1,320.00	1,000
			\$ 4,850.00
			\$ 14,177.91
	GRAND TOTAL		

2080

Adria Lj
23/07/20

06 Days

total: 5875.08

L/S: A7K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: