

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007576/KRA3Q2
Date: 19/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993972		
Claimant Vehicle No :	SMG8251Z	Insured Vehicle No :	GBG4215K		
Date of Loss:	16/07/2020	Nature of Claim:	TP	Claim No:	0236852354SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG8251Z		
Make & Model:	JAGUAR E-PACE, 2.0 S (A)	Engine No:	181003Y0264PT204
Reg. Date:	31/12/2018 (Man. Year: 2018)	Chassis No:	SADFA2AX4K1Z45338
Colour:	White	Odometer:	20616 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,649.55	9,963.15	2,686.40	21.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	2,390.00	1,610.00	40.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,649.55	12,353.15	4,296.40	25.80
+ GST 7.00/7.00% (S\$)	1,165.47	864.72	300.75	25.81

Nett Amount (S\$)	17,815.02	13,217.87	4,597.15	25.80
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		14,025.32		

INSPECTION

Date of Assignment: 22/07/2020

Date Inspected: 28/07/2020

Estimated Period of Repair: 7.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN WITH MOULDING (WCP)	Mldg Necessary	950.00 F	*950.00 F
2	1		*TAILGATE (WCP)	Bent	1,650.00 F	*1,650.00 F
3	1		*TAILGATE EMBLEM (WCP)	Necessary	105.00 F	*105.00 F
4	1		*TAILGATE E-PACK LOGO (WCP)	Necessary	105.00 F	*105.00 F
5	1		*TAILGATE AWD LOGO (WCP)	Necessary	105.00 F	*105.00 F
6	1		*TAILGATE LAMP LH (WCP)	Broken	310.00 F	*310.00 F
7	2		*TAILGATE NO PLATE LAMP LH & RH (WCP)	Serviceable	39.00 F	*- F
8	1		*TAILGATE REVERSE CAMERA (NPA) (WCP)	Serviceable	0.00 F	*- F
9	1		*TAILGATE REVERSE CAMERA COVER (WCP) (NPA)	Serviceable	0.00 F	*- F
10	2		*TAILGATE ABSORBER LH & RH (NPA) (WCP)	Serviceable	0.00 F	*- F
11	1		*TAILGATE SENSOR LH (NPA) (WCP)	Serviceable	0.00 F	*- F
12	1		*TAILGATE LOCK (NPA) (WCP)	Repair	0.00 F	*- F
13	1		*TAILGATE LOCK COVER (NPA) (WCP)	Serviceable	0.00 F	*- F
14	1		*TAILGATE LOCK ACTUATOR (WCP)	Serviceable	95.00 F	*- F
15	1		*TAILGATE RUBBER (WCP)	Cut	120.00 F	*120.00 F
16	1		*TAILGATE INNER TRIMBOARD (WCP)	Mtg Cracked	330.00 F	*330.00 F
17	1		*TAILLAMP LH (WCP)	Cracked	354.00 F	*354.00 F
18	1		*REAR BUMPER (WCP)	Bent	1,150.00 F	*1,150.00 F
19	1		*REAR BUMPER SIDE RETAINER UPPER LH (WCP)	Cracked	60.00 F	*60.00 F
20	1		*REAR BUMPER SIDE RETAINER OUTER LH (WCP)	Serviceable	65.00 F	*- F
21	15		*REAR BUMPER SIDE CLIPS (NPA) (WCP)	Serviceable	0.00 F	*- F
22	1		*REAR BUMPER LOWER GARNISH CENTER (WCP)	Serviceable	175.00 F	*- F
23	1		*REAR BUMPER LOWER GARNISH SIDE LH (WCP)	Dented	40.00 F	*40.00 F
24	1		*REAR BUMPER LOWER MOULDING (SILVER) (WCP)	Serviceable	100.00 F	*- F
25	1		*REAR BUMPER REINFORCEMENT (WCP)	Bent	360.00 F	*360.00 F
26	1		*REAR BUMPER CENTER BRACKET (WCP)	Distorted	80.00 F	*80.00 F
27	1		*REAR BUMPER TOP BRACKET (WCP)	Distorted	105.00 F	*105.00 F
28	1		*REAR BUMPER REVERSE SENSOR OUTER LH (WCP)	Shorted	170.00 F	*170.00 F
29	1		*REAR BUMPER REVERSE SENSOR OUTER HOLDER LH (NPA) (WCP)	Serviceable	0.00 F	*- F
30	1		*REAR BUMPER REVERSE SENSOR INNER LH (NPA) (WCP)	Serviceable	0.00 F	*- F
31	1		*REAR BUMPER REVERSE SENSOR INNER HOLDER LH (NPA) (WCP)	Serviceable	0.00 F	*- F
32	1		*RADAR SENSOR LH (NPA) (WCP)	Serviceable	0.00 F	*- F
33	1		*RADAR SENSOR BRACKET LH (NPA) (WCP)	Serviceable	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*REAR FENDER WHEEL ARCH TRIM LH (WCP)	Distorted	135.00 F	*135.00 F
35	1		*END PANEL OUTER (WCP)	Repair	380.00 F	*- F
36	1		*END PANEL INNER (WCP)	Repair	1,380.00 F	*- F
37	1		*END PANEL TOP GARNISH (NPA) (WCP)	Serviceable	0.00 F	*- F
38	1		*END PANEL REINFORCEMENT PLATE LH (WCP)	Serviceable	78.00 F	*- F
39	1		*END PANEL BUFFER BRACKER LH (WCP)	Repair	24.00 F	*- F
40	1		*REAR EXHAUST PIPE (WCP)	Bent	1,700.00 F	*1,700.00 F
41	1		*REAR EXHAUST CHROME LH (WCP)	Dented	198.00 F	*198.00 F
42	1		*NUMBER PLATE	Dented	35.00 FS	*35.00 FS
43	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
44	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
45	1		*REAR EXHAUST CHROME HEAT SHIELD (WCP)	Bent	86.00 F	*86.00 F
46	1		*REAR EXHAUST MOUNTING (WCP)	Cracked	34.00 F	*34.00 F
47	1		*TAILGATE OUTER (WCP)	Dented	64.00 F	*64.00 F
48	1		*TAILLAMP COVER LH (WCP)	Cracked	100.00 F	*100.00 F
49	1		*REAR BUMPER FOGLAMP LH (WCP)	Broken	135.00 F	*135.00 F
50	1		*REVERSE SENSOR WIRE HARNESS (WCP)	Torn	135.00 F	*135.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	11,012.00	8,676.00
+ Margin on L,N Items 15.00/15.00% (S\$)	1,637.55	1,287.15
Total Parts (S\$)	12,649.55	9,963.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	30.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL CUSHIONS ,SEATS ,BACKREST ,INNER TRIM ,GARNISH ,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	250.00	80.00
4	TO REMOVE AND REINSTALL /REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	60.00	60.00
5	TO REMOVE AND REINSTALL /REPLACE REAR BUMPER SENSORS	New	60.00	60.00
6	TO RESET REAR TAIL BOOT OUTO ABSORBER AND LOCK	New	500.00	180.00
7	TO SPRAY ANTI RUST COATING ON AFFECTED AREAS	New	80.00	0.00
8	TO REALIGN ,DISMANTLE AND REINSTALL /REPLACE EXHAUST PIPE	New	90.00	60.00
9	TO DISMANTLE ALL DAMAGED PARTS ,TO CUT & WELD END PANEL INNER & OUTER TO KNOCK & REPAIR SPARE TYRE PANEL ,INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	1,600.00	900.00
10	TO SPRAY TAILGATE ,REAR BUMPER ,END PANEL ,SPARE TYRE PANEL ,REAR FENDER LH	New	1,200.00	900.00
Gross Labour Cost (S\$)			4,000.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >