

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 4333R**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT WINDSCREEN GLASS	CRACKED	1,533.90	1,533.90
1	FRONT O/S WIPER GARNISH	DENTED	322.00	322.00
1	FRONT N/S WIPER GARNISH	CUT	327.00	327.00
2	WIPER GARNISH SIDE COVER @\$49.30	SERVICEABLE	98.60	-
2	WIPER ARM @\$146.00	DENTED / CUT	292.00	292.00
2	WIPER BLADE @\$59.30	DENTED / CUT	118.60	118.60
1	WIPER MOTOR	SERVICEABLE	374.00	-
1	FRONT DASHBOARD	DENTED / CUT	1,363.00	1,363.00
	LESS 20% DISCOUNT		-885.82	-791.30
			3,543.28	3,165.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	ERP IU SEALANT (SN)	NECESSARY	25.00	25.00
1	FRONT W/S GLASS SOLAR FILM (SN)	NECESSARY	300.00	180.00
			385.00	245.00
<b><u>LABOUR</u></b>				
	TO REMOVE & RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING AND TRANSFER INSTRUMENT FITTINGS.		200.00	180.00
	TO SAND DOWN ROOF TOP, BONNET AND TO POLISH WHOLE CAR.		500.00	400.00
			850.00	700.00
<b>GRAND TOTAL</b>			<b>4,778.28</b>	<b>4,110.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,250.00</b>

Report Ref No. CS/TP20007577/Ksf3e2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.